

Service Repair Sheet SRS68354

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Sudath Weeraman

Prime Lanka Associate

9410718732285

00006714

sudathweeraman17@gmail.com

10/Jan/2023

Robert Connor

Viamed

Warranty

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☐

Cleaned by Viamed,
if no declaration certificate
from customer ☐

Signed: _____
Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____
Date: _____

Notes Would like to return defective MAX 250E sensors, s/n GL08399193 / GL79099109 under warranty

10/Jan/2023 Robert Connor

Received 2 x MAX-250E, s/n GL79099109, GL08399193.

Ready For quote

Repair Complete Signed

CCONOR 11-1-23

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35601	Oxygen Sensor	0110429	GL79099109	Yes
SRN35602	Oxygen Sensor	0110429	GL08399193	Yes

0140013 x 2 FOC
Old S/N's, SRS, SRN's

0110429 x 2 FOC
New S/N's, SRS, SRN

EXW - Skycargo - ship with next order



"Bringing quality to life."

No: 57/8, P.B. Alwis Perera Mawatha, Katubedda,
Moratuwa, Sri Lanka.

+94 071 873 2285 / +94 011 345 9456

011 262 4324

primelanka07@gmail.com
sudathweeraman17@gmail.com

30 December 2022

The Repair Team.

Viamed Ltd, No.15, Station Road, Cross Hills, Keighley
West Yorkshire, BD20 7DT
United Kingdom.

Dear Sir,

The warranty replacement notice, for Oxygen sensor model MAX-250E
Please note below details for your reference.

Model – Oxygen Sensor MAX-250E

1. S/N - GL08399193
2. S/N - GL79099109

Return Reference No. SRS-68354

Thank you,

You're faithfully

S.J. Weeraman

Prime Lanka Associates
No.57/8, P.B.Alwis Perera Mawatha
Katubadda, Moratuwa
Sri Lanka.

Service Repair Sheet 68354

Contact Name

Company/ Hospital Name

Direct Phone

Opera Account

Email

Date Received

Booked in By

Sudath Weeraman

Prime Lanka Associate

9410718732285

00006714

sudathweeraman17@gmail.com

10/Jan/2023

Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35601	0110429	GL79099109	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110429

Replaced under warranty with S/N HF29899039.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35602	0110429	GL08399193	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110429

Replaced under warranty with S/N HF29899040.
