

Service Repair Sheet 68357

|                        |                         |
|------------------------|-------------------------|
| Contact Name           | Paul Cooper             |
| Company/ Hospital Name | Bavaria Blue for Safari |
| Direct Phone           | 0115 943 1430           |
| General Phone          | 0115 9431430            |
| Opera Account          | BAVARIA                 |
| Email                  | pscroyal@outlook.com    |
| Date Received          | 11/Jan/2023             |
| Booked in By           | Robert Connor           |

---

|          |         |      |                        |  |
|----------|---------|------|------------------------|--|
| Repair   | Ref     | S/N  | Equipment Type         |  |
| SRN35603 | 9710203 | 0933 | Oxygen Analyser TEK-OX | Complete - Repaired<br>Time :0.5 Hour(s) |

The TEK-OX analyser has been repaired. The battery contacts have been cleaned. The batteries have been replaced.

---

|          |         |        |                   |   |
|----------|---------|--------|-------------------|---|
| Repair   | Ref     | S/N    | Equipment Type    | Under Warranty                            |
| SRN35604 | 7910201 | TX3600 | Vandagraph Tek Ox | Complete - Repaired<br>Time :0.75 Hour(s) |

The TEK-OX analyser has been repaired. The battery contacts have been cleaned. The batteries have been replaced.  
The case front and case screws have been replaced.

---