

Service Repair Sheet 68335

Contact Name	Shaun Upton
Company/ Hospital Name	M & A Malta
Direct Phone	0035 621585065
Opera Account	CID10822
Email	shaun@mandamalta.com
Date Received	12/Dec/2022
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN35551	7910211	TX1950	Vandagraph Tek Ox	Complete - Repaired Time :0.5 Hour(s)

The Tek-Ox analyser has been repaired. The on/off button and front gasket have been replaced.

Repair	Ref	S/N	Equipment Type	
SRN35552	7910211	TX2170	Vandagraph Tek Ox	Complete - Repaired Time :0.5 Hour(s)

The Tek-Ox analyser has been repaired. The sensor contacts have been cleaned. Some case screws have been replaced.

Repair	Ref	S/N	Equipment Type	
SRN35553	7910211	TX2206	Vandagraph Tek Ox	No Fault Found Time :0 Hour(s)

The Tek-Ox analyser has been tested. No fault was found with the unit or the Oxygen sensor.

Repair	Ref	S/N	Equipment Type	
SRN35554	7910211	TX2595	Oxygen Analyser TEK-OX	Complete - Repaired Time :0.75 Hour(s)

The Tek-Ox analyser has been repaired. The sensor input connector has been replaced.