

Service Repair Sheet SRS68350

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Sean Bunn

Luton & Dunstable Hospital

Clinical Engineering

01582718369

01582 497042

00003490

Sean.Bunn@ldh.nhs.uk

30074418

21/Dec/2022

Robert Connor

Viamed

Repair

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☐

Cleaned by Viamed,
if no declaration certificate
from customer ☐

Signed: _____

Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes Customer has 2x V1000 units they would like to send for a calibration/service - price has been quoted via email.

19/Dec/2022 Sophie Lines

Sean confirmed they will send units in via TNT. Serial numbers: GE71743928 and PR02041A12

21/Dec/2022 Robert Connor

Received 2 x V1000 s/n GE71743926 with battery door, PR02041A12 no battery door.

21/Dec/2022 Catherine Spence

In engineers room

22/Dec/2022 Philip Crossley

1430309 Transducer interface cushion is free with service.

To replace battery door I need to quote a whole case.

03/Jan/2023 Catherine Spence

Quote sent to customer on 23/12/22

11/Jan/2023 Catherine Spence

still on quote

17/Jan/2023 Catherine Spence

on wuote

19/Jan/2023 Kate Griffiths

30074418 PO attached

Ready For quote

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35562	Foetal Simulator	1410000	GE71743928	*
SRN35563	Foetal Simulator	1410000	PR02041A12	

edited
S/N

Please update CUM141067
eg 7-2.2023