

Service Repair Sheet SRS68349

Contact Name
Company/ Hospital Name
Department
Position
Direct Phone
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By
Main Company
Type Return

Ayelet Mor
I.M.T.C Ltd

972 866 36637
(972)86636637
00007088
Ayelet@imtc.co.il

07/Feb/2023
Robert Connor
Viamed
Bring To Attention

VIAMEDclear

Goods In Only
Decontamination
certificate provided
by customer

Cleaned by Viamed
if no declaration certificate
from customer
Signed: _____
Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____
Date: _____

Notes 15/Dec/2022 Ryan Swaine

15/Dec/2022 Ryan Swaine

5x R-49V reported to be faulty and will not calibrate on the RAFAEL VELLA VISTA

This is the sn:

V102577

V102542

V102697

V102574

V102580

07/Feb/2023 Robert Connor

Received 5 x R-49 s/n V102542, V102574, V102577, V102580, V102697.

Ready For quote

CGreen 10.2.23

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35633	Oxygen Sensor	0110049	V102542	2
SRN35634	Oxygen Sensor	0110049	V102574	2
SRN35635	Oxygen Sensor	0110049	V102577	2
SRN35636	Oxygen Sensor	0110049	V102580	2
SRN35637	Oxygen Sensor	0110049	V102697	Yes

0140015 x 4

old S/N, SRS, SEN

0110049 x 4 @ €36 each
SRS, SEN

9149913241

or ship with

INTERNATIONAL MEDICAL TRADE & CONSULTANTS Ltd.

PHONE:(972)086636637; FAX:(972)086767603 MAIL: imtc@imtc.co.il

Faran 2, Yavne, ISRAEL

P.O.B. 8508; Rishon Le-Zion; ISRAEL

COMMERCIAL INVOICEV.A.T REGISTRATION # 512666421**January 24, 2023****Invoice no.: PO2541**

Viamed Ltd
15 Station Road
Cross Hills
Keighley, West Yorkshire
BD20 7DT, United Kingdom
Tel: +44 (0) 1535 634542
Mobile +44 0 7803907117
Fax: +44 (0) 1535 635582
Email: info@viamed.co.uk

Attn: Mr. Ryan Swaine – International sales manager
RETURNS REF – SRS68349


ITEM	QTY	DESCRIPTION	UNIT PRICE EURO	TOTAL PRICE EURO
1	5	Oxygen sensor 0110049 SN V102577 V102542 V102697 V102574 V102580	25	125
Total				125

Notes :

Faulty items return to mfr. For repair/ exchange.

Value for custom purpose: 125 EURO

Signature: _____
International Medical Trade & Consultants Ltd.
(P.O.B. 8508, Rishon Le-Zion, ISRAEL)

**Select Currency**Pounds| Euros | Usd**Repair SRS68349 Values in Euros @ €1.14410: €1.00**

SRN35633	Oxygen Sensor	0110049			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		0110049	1	€48.05	€48.05
SRN35634	Oxygen Sensor	0110049			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		0110049	1	€48.05	€48.05
SRN35635	Oxygen Sensor	0110049			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		0110049	1	€48.05	€48.05
SRN35636	Oxygen Sensor	0110049			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		0110049	1	€48.05	€48.05
				Parts Cost	€192.21

36€

36€

36€

36€

cg 10-2-23

CHECK PRICES BEFORE SENDING QUOTE

Quote Sent