

Service Repair Sheet SRS68385

Contact Name

Janet Driver

Company/ Hospital Name

Barnet Hospital

Department

Position

Direct Phone

02082164978

General Phone

0208 2164978

Opera Account

00000261

Email

janet.driver@siemens-healthineer

Order Number

Date Received

13/Feb/2023

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☐

Cleaned by Viamed,
if no declaration certificate
from customer ☐

Signed: _____
Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____
Date: _____

Notes 08/Feb/2023 Aqib Majeed

08/Feb/2023 Aqib Majeed

SN number is 101036 as per customer pdf attached

08/Feb/2023 Aqib Majeed

Returning a Foetal Heart Simulator for calibration

13/Feb/2023 Robert Connor

Received 1 x V1000 s/n PR02315A14, with 4 x AA battery and blue fabric cover.

Ready For quote

CCGreen 14.2.23

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35642	Foetal Simulator	1410000	PR02315A14	2

1480001 x 1 @ £35

S/N, SRS, SRN

UPS x 1 @ £10.

EQUIPMENT RETURNS PENDING NUMBER

2023/023

RMA / REF: _____

SHIP TO
VIAMED LTD
15 STATION ROAD, CROSSHILLS
KEIGHLEY
WEST YORKSHIRE
BD20 7DT
0153 563 4542

JOB NUMBER: 600823
DESCRIPTION: Foetal Heart Simulator
MODEL: Viamed
FAULT DESCRIPTION: Calibration Required
ACCESSORIES: _____

ASSET No: 1010010600
SERIAL No: PRO2315A14

Please advice cost prior to carrying out repairs.

Please note that a service report should accompany the equipment where appropriate.
To avoid delay in payment the invoice should be sent to Siemens plc c/o Data Capture Solution,
PO Box 4728, Slough, SL1 0AE.

Yours Faithfully,

Jan Driver
Equipment Librarian
janet.driver@siemens-healthineers.com
Please Cc: Barnet.MES.med.gb@siemens-healthineers.com
Tel: 020 8216 4978

Declaration of Contamination Status

Was the item contaminated?

Yes ☐ No ☒ Don't know ☐

Type of contamination: (e.g. Blood, body fluids, chemicals etc.)

Has the item been decontaminated?

Yes ☒ No ☐ Don't know ☐

Method of decontamination:

Cleaning

Disinfection

Sterilisation (if applicable)



Wiped with clinell

Please explain why the items has NOT been decontaminated: (if applicable)

n/a

20.00 °C

Search



Select Currency

[Pounds](#) | [Euros](#) | [Usd](#)
Repair SRS68385 Values in Pounds @ £1: £1.00

SRN35642	Foetal Simulator	1410000			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		1480001	1	£35.00	£35.00
				Parts Cost	£35.00

CHECK PRICES BEFORE SENDING QUOTE