



Stornoway Subsea Ltd

 CID17142 Opera Type: **Vandagraph Retail**
Stornoway Subsea Ltd Nacula 8C, Steinish, Isle of Lewis, , HS2
 0AA, Scotland
 Tel **07880892936** GBP Retail Price List Vandagraph (0010)
[Log Call](#) [Add Issue](#)
 Proforma Credit Limit 0.00GBP

Proforma Credit Limit 0.00GBP

 Account Home

 Main Details

Account Memos

 Sales History

 Purchase Orders

Stock References

🔄 Cust./Supp. Returns

Service Visits

Distributor Agreements

Documents
Files

 **Linked Issues**

Regulatory Agreements

SRS68419

SRS Created : 13 Mar 2023
Created By Robert Connor
Add Watch

[Print Barcodes](#)
[Print A4 Sheet](#)
[Split Items into Different SRS Numbers](#)

Upload Document to SRS

Handle with care
Add Items to Supplier Returns Box

☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs

☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

Add Notes

ADD DOCUMENT TO SRS : Document Description	Choose a file to upload: Choose file No file chosen
Next	

Next

Service Repair Sheet 68419	
Company / Hospital	Stornoway Subsea Ltd
Contact Name	Don Macdonald
Department	
Position	
Company Phone	07880892936
Direct Phone	
Opera Account	
Email	donmacdonald21@hotmail.com
Order Number	
Viamed ORD Number	
Date Received Into building	13 Mar 2023
Type	Quote Before Repair
Issues?	289523

Notes

13/Mar/2023 Robert Connor

13/Mar/2023 Robert Connor
Received 1 x tek-ox s/n 2611, in yellow carry case, with blue tee.

LINKED ISSUE NOTES:
289523:
AutoGenerated Issue SRS68419 Appears to be Complete

Items for Repair

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN35697	Vandagraph Tek Ox	7910211	 1183092	TX2611	Oxygen Analyser	No	No	Complete - Repaired	Battery Contacts	00:30

15/03/2023, 12:14

SRS View

					Tek-Ox			15 Mar 2023 Michael Green		
SRN35697 Engineer Notes: INTERNAL NOTES not for customer discussion 15/Mar/2023 Michael Green The Tek-Ox analyser has been repaired. The battery door battery contact has been replaced. The batteries have been replaced.										

Currently Viewing ITEM SRN35697 Vandagraph Tek Ox 7910211 TX2611 Oxygen Analyser Tek-Ox

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The Tek-Ox analyser has been repaired. The battery door battery contact has been replaced. The batteries have been replaced.	15/Mar/2023 Michael Green The Tek-Ox analyser has been repaired. The battery door battery contact has been replaced. The batteries have been replaced.	The Tek-Ox analyser has been repaired. The battery door battery contact has been replaced. The batteries have been replaced.

1