

Service Repair Sheet SRS68402

Contact Name
Company/ Hospital Name
Department
Position
Direct Phone
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By
Main Company
Type Return

Carey Halliday
Brennan & Co NI

Business Support Officer

02890410136
00012907
Challiday@brennanconi.com

06/Mar/2023
Robert Connor
Viamed
Quote

VIAMEDclean	
Goods In Only	
Decontamination certificate provided by customer	<input type="checkbox"/>
Cleaned by Viamed, if no declaration certificate from customer	<input checked="" type="checkbox"/>
Signed: <u>RC</u>	
Date: <u>6/3/23</u>	
Goods Out Only	
Cleaned by Viamed before returning to customer	
Signed: _____	
Date: _____	

Notes 27/Feb/2023 Kate Griffiths

27/Feb/2023 Kate Griffiths

Would like to send in MaxO2 ME for calibration next week. S/n: FA75699022

06/Mar/2023 Robert Connor

Received 1 x MAXO2ME s/n FA75699022, with 4 x AA battery, coiled cable ID 1454195, and MAX-550E s/n HH65699183, with flow diverter.

Ready For quote

CGreen 14.3.23

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35693	Oxygen Monitor	0111263	FA75699022	2
SRN35694	Oxygen Monitor Cable	0131700	Tracking7	2
SRN35695	Oxygen Sensor	0110452	HH65699183	Yes

0180020 x 1 £40.00

S/N, SRS, SRN

UPS x 1 @ ~~£12~~

32x26x12cm
0.60kg

sorry forgot it was
northern Ireland.

Use cheapest service eg 17-3-23