

Service Repair Sheet SRS68338

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Ryan Chapman

Darlington Memorial Hospital

Clinical Engineering Department

Clinical Engineering Technician

01325743048

00001350

ryan.chapman@nhs.net

22/Mar/2023

Robert Connor

Viamed

Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☐

Cleaned by Viamed,
if no declaration certificate
from customer ☐

Signed: _____

Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 30/Nov/2022 Kate Griffiths

30/Nov/2022 Kate Griffiths

Customer would like Tom Thumb to be serviced, s/n VMDI06. I am unable to find this s/n on i/stats

22/Mar/2023 Robert Connor

Received 1 x tom thumb s/n VMDI06, box labelled as depleted sensors with no paperwork.

Ready For quote

CCGreen 22.3.23


Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35709	Tom Thumb	0310030	VMDI06	N

0380000 x 1 @ £90

S/N, SRS, SRN

UPS x 1 @ £12.



Select Currency

[Pounds](#) | [Euros](#) | [Usd](#)

Repair SRS68338 Values in Pounds @ £1: £1.00

SRN35709	Tom Thumb	0310030			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		0380000	1	£90.00	£90.00
				Parts Cost	£90.00

CHECK PRICES BEFORE SENDING QUOTE

Quote Sent