

# Service Repair Sheet SRS68424


Contact Name  
Company/ Hospital Name  
Department  
Position  
Direct Phone  
General Phone  
Opera Account  
Email  
Order Number  
Date Received  
Booked in By  
Main Company  
Type Return

Jomon Joseph  
Luton & Dunstable Hospital  
  
Clinical Engineer  
01582 718 369  
01582 497042  
00003490  
ceworkshop@ldh.nhs.uk  
  
20/Mar/2023  
Robert Connor  
Viamed  
Bring To Attention


## VIAMEDclean

### Goods In Only

Decontamination  
certificate provided  
by customer



Cleaned by Viamed,  
if no declaration certificate  
from customer



Signed: \_\_\_\_\_  
Date: \_\_\_\_\_

### Goods Out Only

Cleaned by Viamed before  
returning to customer

Signed: \_\_\_\_\_  
Date: \_\_\_\_\_

Notes 20/Mar/2023 Robert Connor

20/Mar/2023 Robert Connor

Received 1 x VM-2500-S s/n A1711160006, with 4 x AA battery and silicone cover.

Ready For quote

CCGreen 24.3.23

Repair Complete Signed

\_\_\_\_\_

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35704	Capnograph	4410520	A1711160006	2

4440000 x 0.5 @ £90 per hour

S/N, SRS, SRN

UPS x 1 @ £12.

Reference:

Work Requested: Repair and Calibration


Hospital

<b>Hospital</b>	<b>Luton &amp; Dunstable University Hospital</b>
<b>Address</b>	<b>Lewsey Road, Luton, LU4 0DZ</b>
<b>Phone Number</b>	<b>01582 718 369</b>
<b>Email Address</b>	<b>CEWorkshop@ldh.nhs.uk</b>

Device

<b>Asset no</b>	31033
<b>Serial Number</b>	A1711160006
<b>Model</b>	VM-2500-S
<b>Description of device</b>	CO2 MONITOR
















Sender

<b>Name</b>	JOMON JOSEPH
<b>Signature</b>	
<b>Position</b>	CLINICAL ENGINEER

Receiver

<b>FAO</b>	Janine Gill
<b>Company</b>	VIAMED LTD
<b>Phone</b>	+44 (0)1535 634 542
<b>Email</b>	<a href="mailto:janine.gill@viamed.co.uk">janine.gill@viamed.co.uk</a>





SN Future Active Users 22.00 °C

Barcodes / SN

Search



## Select Currency

Pounds| Euros| Usd

## Repair SRS68424 Values in Pounds @ £1: £1.00

SRN35704	Capnograph	4410520			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		4440000	0.5	£90.00	£45.00
				Parts Cost	£45.00

## CHECK PRICES BEFORE SENDING QUOTE

Quote Sent