Service Repair Sheet SRS68402

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Carey Halliday

Brennan & Co NI

**Business Support Officer** 

02890410136

00012907

Challiday@brennanconi.com

06/Mar/2023

Robert Connor

Viamed

Quote



Notes 27/Feb/2023 Kate Griffiths

27/Feb/2023 Kate Griffiths

Would like to send in MaxO2 ME for calibration next week. S/n: FA75699022

06/Mar/2023 Robert Connor

Received 1 x MAXO2ME s/n FA75699022, with 4 x AA battery, coiled cable ID 1454195, and MAX-550E s/n HH65699183, with flow diverter.

Ready For quote

Repair Complete Signed

Careen 14.3.23

agreen 28.3.23

29.3.23

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35693	Oxygen Monitor	0111263	FA75699022	2
SRN35694	Oxygen Monitor Cable	0131700	Tracking7	2
SRN35695	Oxygen Sensor	0110452	HH65699183	Yes

0180020 × 1 EA0.00 5/N, 5RS, SRN est as per memoion goode as distibuter cy 17-3-23

UPS X 1 2 ft. 27 32 x 26 x 12 cm 0.60 kg sorry forget is was
northern ireland.
Use aneapest service cg 17-3-23

PLEASE ADD-1 missed these off.

C9 29.3.23.

0140025 X 10 £0 5/N, 5RS, 5RN 0140011 X1 2 £0. 5/N, 5RS, 5RN