

Service Repair Sheet SRS68347

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Lisa Vickers

Medivent Ltd (Euro)

016280338

0035316280338

00007374

info@medivent.ie

14/Dec/2022

Robert Connor

Viamed

Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☐

Cleaned by Viamed,
if no declaration certificate
from customer ☐

Signed: _____
Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____
Date: _____

Notes 12/Dec/2022 Kate Griffiths

12/Dec/2022 Kate Griffiths

To return 2 x VM-2500 S, s/n: A171116004 and A1809150028. Have asked if A171116004 has a digit short and asked what is wrong with them.

12/Dec/2022 Kate Griffiths

UPDATE: s/n should be A1711160004

12/Dec/2022 Kate Griffiths

UPDATE: "both are reading low ETCO2, one displays malfunction on the screen"

14/Dec/2022 Robert Connor

Received 2 x VM-2500-S s/n A1711160004, A1809150028, with 8 x AA battery.

A1711160004 has a broken power connector, pins intact but plastic keyway is half missing.

Ready For quote

CGN 19.12.22

Repair Complete Signed

€

Quote 1

full calibration -
at least 3 weeks

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35556	Capnograph	4410520	A1809150028	N
SRN35557	Capnograph	4410520	A1711160004	N

no calibration
check.

Quote 2

4440000 x 1 @ 0.50hr @ €35 per 1/2
S/N, SRS, SRN

4440000 x 1 @ 0.75hr @ €70 per hr
S/N, SRS, SRN → SRN 35557

4430201 x 1 @ €17.45 each
SRS, SRN'S

4480520 x 1 @ €90 each
SRS, SRN

4400070 x 1 @ €49.17
SRS, SRN

UPS → Need to Add. *
4420504 x 1 @ 950€
SRS, SRN 35557, S

32x26x12cm
1kg

4440000 x 1 @ 0.50hr = €35 per 1/2
S/N, SRS, SRN

4440000 x 1 @ 0.75hr = €70 per hr
S/N, SRS, SRN → SRN 35557

4430201 x 2 @ €17.45 each
SRS, SRN'S.

4400070 x 1 @ €49.17
SRS, SRN

UPS.
32x26x12cm 1kg