

Service Repair Sheet SRS68349

Contact Name

Ayelet Mor

Company/ Hospital Name

I.M.T.C Ltd

Department

Position

Direct Phone

972 866 36637

General Phone

(972)86636637

Opera Account

00007088

Email

Ayelet@imtc.co.il

Order Number

Date Received

07/Feb/2023

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Bring To Attention

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☐

Cleaned by Viamed,
if no declaration certificate
from customer ☐

Signed: _____

Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 15/Dec/2022 Ryan Swaine

15/Dec/2022 Ryan Swaine

5x R-49V reported to be faulty and will not calibrate on the RAFAEL VELLA VISTA

This is the sn:

V102577

V102542

V102697

V102574

V102580

07/Feb/2023 Robert Connor

Received 5 x R-49 s/n V102542, V102574, V102577, V102580, V102697.

Ready For quote

CGreen 10.2.23

Repair Complete Signed

CGreen 21.4.23

US \$

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35633	Oxygen Sensor	0110049	V102542	2
SRN35634	Oxygen Sensor	0110049	V102574	2
SRN35635	Oxygen Sensor	0110049	V102577	2
SRN35636	Oxygen Sensor	0110049	V102580	2
SRN35637	Oxygen Sensor	0110049	V102697	Yes

Sold July 21
15 Sept 21 / 15 Dec 21
15 Sept 21 Rnd
15 Sept 21
26.2.21

Jan 22.

0140015 x 4

old S/N, SRS, SRN

0110049 x 4 @ £36 each. \$37.75.
S/N SRS, SRN - SRN 35633-35635.

* Add old 0140013 x 1 FOC
S/N, SRS, SRN
0110049 x 1 FOC New S/N, SRS, SRN
OPS: 32x26x12cm @ 0.60kg

for the items of
warranty
only CG 21.4.23

* please ac
Extra Lines
CG 21.4.23
or ship with
next order ex

INTERNATIONAL MEDICAL TRADE & CONSULTANTS Ltd.
PHONE:(972)086636637; FAX:(972)086767603 MAIL: imtc@imtc.co.il

Faran 2, Yavne, ISRAEL
P.O.B. 8508; Rishon Le-Zion; ISRAEL

COMMERCIAL INVOICE

V.A.T REGISTRATION # 512666421

January 24, 2023

Invoice no.: PO2541

Viamed Ltd
15 Station Road
Cross Hills
Keighley, West Yorkshire
BD20 7DT, United Kingdom
Tel: +44 (0) 1535 634542
Mobile +44 0 7803907117
Fax: +44 (0) 1535 635582
Email: info@viamed.co.uk

Attn: Mr. Ryan Swaine – International sales manager
RETURNS REF – SRS68349

ITEM	QTY	DESCRIPTION	UNIT PRICE EURO	TOTAL PRICE EURO
1	5	Oxygen sensor 0110049 SN V102577 V102542 V102697 V102574 V102580	25	125
Total				125

Notes :

Faulty items return to mfr. For repair/ exchange.
Value for custom purpose: 125 EURO

Signature of International Medical Trade & Consultants Ltd.
(P.O.B. 8508, Rishon Le-Zion, ISRAEL)

Service Repair Sheet 68349

Contact Name	Ayelet Mor
Company/ Hospital Name	I.M.T.C Ltd
Direct Phone	972 866 36637
General Phone	(972)86636637
Opera Account	00007088
Email	Ayelet@imtc.co.il
Date Received	07/Feb/2023
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	End Of Life
SRN35633	0110049	V102542	Oxygen Sensor	Time :0 Hour(s)

Parts Replaced
Qty: 1 0110049

Replaced with S/N V103240

Repair	Ref	S/N	Equipment Type	End Of Life
SRN35634	0110049	V102574	Oxygen Sensor	Time :0 Hour(s)

Parts Replaced
Qty: 1 0110049

Replaced with S/N V103241

Repair	Ref	S/N	Equipment Type	End Of Life
SRN35635	0110049	V102577	Oxygen Sensor	Time :0 Hour(s)

Parts Replaced
Qty: 1 0110049

Replaced with S/N V103242

Repair	Ref	S/N	Equipment Type	End Of Life
SRN35636	0110049	V102580	Oxygen Sensor	Time :0 Hour(s)

Parts Replaced
Qty: 1 0110049

Replaced with S/N V103243

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35637	0110049	V102697	Oxygen Sensor	Time :0 Hour(s)

Parts Replaced
Qty: 1 0110049

Replaced under warranty with S/N V103115