Service Repair Sheet SRS68440

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Daniel Lodge

Royal Liverpool University Hospita

Medical Engineering Department

0151 7062079

0151 706 2000

00002690

daniel.lodge@liverpoolft.nhs.uk

25/Apr/2023

Robert Connor

Viamed

Quote



Notes 14/Apr/2023 Janine Gill

14/Apr/2023 Janine Gill

The customer has an AX300 with the serial number 339155 that keeps showing the alarm sensor and showing zero. Sent SRS number with info to send it to us.

25/Apr/2023 Robert Connor

Received 1 x AX300i s/n 339155, coiled cable s/n 0010470, R-17MED s/n 605862, flow diverter, and 3 x AA battery.

Ready For quote

CGreen 26.4.23

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35760	Oxygen Monitor	0111230	339155	2
SRN35761	Oxygen Monitor Cable	0131202	0010470	2
SRN35762	Oxygen Sensor	0110017	605862	2

5/N, SRS, SRN

0140025 × 1 FOC NO faut found. SIN, SRS, SRN

210,5/N, SRS, SRN

0110017 × 1 & £53.00

SRS, SRN

1705 X 1 @ E12.

SRS68440

Daniel Lodge

Disi 706 2079

Royal Live, pool Hospital,

Mount Vernon Street,

Liverpool,

L7 8YE

Alarming V Sensor wont show readings changed sensor however still alarming



meetings opera

Select Currency

Pounds Euros Usd

Repair SRS68440 Values in Pounds @ 1: 1.00

SRN35762	Oxygen Sensor	0110017			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		0110017	1	4 2.00	4 2.00
	and Attitudes of Street, St.			Parts Cost	4 2.00

CHECK PRICES BEFORE SENDING QUOTE

Quote Sent