

Service Repair Sheet SRS68461

Contact Name
Company/ Hospital Name
Department
Position
Direct Phone
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By
Main Company
Type Return

Dean Young
Hull Royal Infirmary
Medical Physics
Technician
01482 608973

00002265
dean.young@hey.nhs.uk

15/May/2023
Robert Connor
Viamed
Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer



Cleaned by Viamed,
if no declaration certificate
from customer

Signed: _____

Date: _____



Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 09/May/2023 Sophie Lines

09/May/2023 Sophie Lines

Has 2x Tom Thumb units requiring repair - he has given serial numbers as follows (I have not found anything on the system under these):

VMCJ55 - Guage is reading inaccurate

440060 - Adjustable valve faulty and end nut missing

15/May/2023 Robert Connor

Received 2 x tom thumb s/n 440060, VMCJ55

Ready For quote

CGreen 17-5-23

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35786	Tom Thumb	0310030	VMCJ55	22
SRN35787	Tom Thumb	0310030	440060	

0380000 x 2 @ £90 each

SIN, SRS, SRN

0330203 x 1 @ £125

SRS, SRN

0330207 x 1 £2.

SRS, SRN

0330227 x 1 £12.

SRS, SRN

UPS x 1 @ £12

Department of Clinical Engineering

Head of Service:

Prof A W Beavis

PhD BSc CPhys CSci MInstP MloD FIPEM FBIR HPC reg number CS0162 (Hon) Reader, Hull and York Medical School

Date : 10-05-2023

Job Reference : 367433

SRS68461
Viamed Ltd
15 Station Road
Cross Hills
BD20 7DTEquipment Details

Description : Tom Thumb

Serial Number : 440060

Fault : Adjustable valve faulty, end nut missing and service required


Action Required

Please find enclosed the above faulty unit requiring a quotation for repair.

If there are to be any charges associated with investigations or repair they should be notified to the Clinical Engineering Department before commencing.

Any work undertaken without an order number will not be paid.

Signature



Dean Young

Return AddressMedical Physics Department
The Tulley Building
Hull Royal Infirmary
Anlaby Road
Kingston upon Hull
East Yorkshire
HU3 2JZ


☎ 01482 608965

✉ hyp-tr.ce.hullroyalinfirmaty@nhs.net

Parts in Package**Remarkable people.**
Extraordinary place.

www.hull.nhs.uk | facebook.com/hullhospitals | twitter.com/hullhospitals

Catherine Spence Required Reading **1 Calls** 33 Issues 23 **Unread** 19 ISO Tasks
 | H/W. SH(m) Future Active Users 24.00 °C Stock Search



Select Currency

Pounds| Euros| Usd

Repair SRS68461 Values in Pounds @ £1: £1.00

SRN35786	Tom Thumb	0310030			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		0380000	1	£90.00	£90.00
		0330203	1	£125.00	£125.00
SRN35787	Tom Thumb	0310030			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
	E2. 0330207	0330207	1	£0.00	£0.00
		0330227	1	£12.00	£12.00
		0380000	1	£90.00	£90.00
				Parts Cost	£317.00

Passed
 back to
 Engineer
 17-5-23

E2 as agreed
 with SN.
 18-5-23

CHECK PRICES BEFORE SENDING QUOTE

Quote Sent