

Service Repair Sheet SRS68455

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Clay Harper

Sage Services Group

VP of Operations

8772817243

00006727

clay@sageservicesgroup.com

10/May/2023

Robert Connor

Viamed

Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☒

Cleaned by Viamed,
if no declaration certificate
from customer ☐

Signed: _____

Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 05/May/2023 Kate Griffiths

05/May/2023 Kate Griffiths

Requires V1000 calibration, s/n PR02516A10

10/May/2023 Robert Connor

Received 1 x V1000 s/n PR02516A10

Ready For quote

CGreen 11.5.23

Repair Complete Signed

CGreen 18.5.23

USD

End

User

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35776	Foetal Simulator	1410000	PR02516A10	N

1480000 x 1 @ \$55.00

SIN, SRS, SRN


1480000 x 1 @ \$0.00

SRS, SRN

INS

UPS x 1 @

32x24-12cm wgt-1.20kg



Date	P.O. No.
5/5/2023	103539

Ship To
Sage Services Group 2160 Hwy 292 Inman, SC 29349

Expected Date
5/5/2023

Total	\$0.00
--------------	--------

Phone #	Fax #	E-mail	Web Site
(843) 284-5844	(866) 345-5544	Sales@SageServicesGroup.com	www.sageservicesgroup.com

Service Repair Sheet 68455

Contact Name	Clay Harper
Company/ Hospital Name	Sage Services Group
Position	VP of Operations
General Phone	8772817243
Opera Account	00006727
Email	clay@sageservicesgroup.com
Order Number	Paid proforma
Date Received	10/May/2023
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type
SRN35776	1410000	PR02516A10	Foetal Simulator

Complete - Repaired
Time :0 Hour(s)

Parts Replaced

Qty: 1	1430309
Qty: 1	1480000

V1000 has had transducer interface cushion replaced and calibration has been checked

Service Repair Sheet 68455

Contact Name	Clay Harper
Company/ Hospital Name	Sage Services Group
Position	VP of Operations
General Phone	8772817243
Opera Account	00006727
Email	clay@sageservicesgroup.com
Order Number	Paid proforma
Date Received	10/May/2023
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type
SRN35776	1410000	PR02516A10	Foetal Simulator

Complete - Repaired
Time :0 Hour(s)

Parts Replaced

Qty: 1	1430309
Qty: 1	1480000

V1000 has had transducer interface cushion replaced and calibration has been checked
