

Service Repair Sheet SRS68486

Contact Name
Company/ Hospital Name
Department
Position
Direct Phone
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By
Main Company
Type Return

Terry Millen
University Hospital Crosshouse
Medical Physics Department

01563826080
01563 21133
00001320
terry.millen2@aapct.scot.nhs.uk

07/Jun/2023
Robert Connor
Viamed
Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☒

Cleaned by Viamed,
if no declaration certificate
from customer ☐

Signed: _____

Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 06/Jun/2023 Steve Hardaker

06/Jun/2023 Steve Hardaker

Returning a high-flow MaxBlend for repair, s/n TE00000034, the reed valve is not alarming.

I have asked Jim at Maxtec whether the parts are still available or if these can be repaired and serviced with MaxBlend 2 parts.

07/Jun/2023 Robert Connor

Received 1 x Maxblend s/n TL00000034, with MAX250E s/n FG40399059, plus flow diverter.

Ready For quote

CGreen 9.6.23

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35818	Blender		TL00000034	2
SRN35819	Oxygen Sensor	0110429	FG40399059	2

0380061 x 1 @ £180
SIN, SRS, SRN

R200P02 x 1 @ £270
SRS, SRN

~~0110429 x 1 @ £69~~

0140012
~~0140012~~ x 1 @ £12
old SIN, SRS, SRN.

0110429 x 1 @ £69
New SIN, SRS, SRN

UPS x 1 @ £12.

NHS Ayrshire & Arran
University Hospital Crosshouse - Medical Physics Department

**Ayrshire
& Arran**

From: Mr Terry Millen Clinical Technologist Contact: T: Helpdesk 01563 827456 T: 01563 826080 E: terry.millen2@aapct.scot.nhs.uk E: Clinical_MedicalPhysics_XH@aapct.scot.nhs.uk	Address: Medical Physics University Hospital Crosshouse Kilmarnock Road Kilmarnock Scotland, UK KA2 0BE
--	--

Job No:	212925	Date	06 June 2023
Equipment No:	17240	Site:	Crosshouse
Serial No:	TL00000034	Location:	ACCU
Brand:	Maxtec	Contact Telephone:	01563 826080
Model:	Maxblend High Flow	Contact Name:	Terry Millen
Category:		Purchase Order No:	
Reported Fault:	Safety feature failure and service <div style="font-size: 2em; font-family: cursive;">SRS 68486</div>		

Return of Equipment or Goods

The Medical Physics Department must be informed of the repair cost; prior to any chargeable work being carried out.

Please turn over for contamination status.

Declaration of Contamination Status


Medical Physics Department, University Hospital Crosshouse, Kilmarnock, KA2 0BE

Version 00.1 (XH)

Date approved 02/10/2018

Author: Morag Ross

Required Reading **1 Calls** 40 Issues **27 Unread** 24 ISO Tasks
 | H/W. Future Active Users 21.00 °C



Select Currency

Pounds| Euros | Usd

Repair SRS68486 Values in Pounds @ £1: £1.00

SRN35818	Blender				
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		0380061	1	£0.00	£0.00
		R200P02	1	£0.00	£0.00
SRN35819	Oxygen Sensor	0110429			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		0110429	1	£66.00	£66.00
				Parts Cost	£66.00

£180
£270

£69
cg 9-6-23
as per
Intrasts.

CHECK PRICES BEFORE SENDING QUOTE

Quote Sent