



Honeywell Healthcare Solutions GmbH

CID4348 Opera 00007282 Type: Company Supplier Customer
 Honeywell Healthcare Solutions GmbH Alter Holzhafen 18, Wismar,
 , D-23966, Germany
 Tel 0049 3841 360204 Euro Distributor (0004) Log Call

Add Issue

VAT DE137437213

Account Home	Main Details	Account Memos	Sales History	Purchase Orders	Supplier Returns	Stock References	Cust./Supp. Returns	Service Visits
Distributor Agreements	Documents Files	Linked Issues	Regulatory Agreements					

BOX:917

Manufacturer RMA : 300264434

☒ Repaired ☐ No Fault Found

Returned Barcode

Close File 917

Tick All Replaced

Review	Stock Ref	Sup Ref	B/C	S/N	Fault	Replaced	No Fault Found	Repaired	Credited	Out Warranty	Returned Unrepaired	Notes
Review 8010008 Customer Stats	8010008		2118225	M01111704	No Output Country of Origin: Germany Customs Value: 5.00 euro	☐	☐	☐	☒	☐	☐	
Review 8010012 Customer Stats	8010012		2196374	ISC117179	Low Output Country of Origin: Germany Customs Value; 5.00 euro	☐	☐	☐	☒	☐	☐	

Update Returns

Customer Failure Statistics

Start From 19/06/2021 End at 19/06/2023

Invoice Correction 5263812815

ORIGINAL

Invoice Correction Date: 07.06.2023

Honeywell Healthcare Solutions GmbH

Alter Holzhafen 18

Purchase Order No: RTS3100917

23966 Wismar

Germany

Billed to: 1797448
Vandagraph Sensor Technologies Ltd.
15 Station Road
Cross Hills, West Yorkshire
KEIGHLEY
BD20 7DT
United Kingdom

Sold to: 1797448
Vandagraph Sensor Technologies Ltd.
15 Station Road
Cross Hills, West Yorkshire
KEIGHLEY
BD20 7DT
United Kingdom

Order Information:
Credit Memo Request: 64085054
Sales Office: 2170 DE SPS Wismar
Incoterms: FCA Origin
Payment Terms: Net 30 Days After Invoice Date

Ship to: 1797448
Vandagraph Sensor Technologies Ltd.
15 Station Road
Cross Hills, West Yorkshire
KEIGHLEY
BD20 7DT
United Kingdom

EM NO.	Material No.	QTY	UOM	UNIT PRICE	EXT. PRICE	VAT %
00010	E1002106 Oxygen Sensor OOD103-ISC Customer Part Nbr: 8010012 credit note for SN: 117179	1	EA	21,52 ✓	-21,52	0%
00020	E1002734 Oxygen Sensor OOD103 VAN 8010008 Customer Part Nbr: 8010008 credit note for SN: 111704	1	EA	19,99 ✓	-19,99	0%

Totals

Total Before VAT	-41,51 EUR
VAT-Total	0,00 EUR
Total Amount	-41,51 EUR

Tax Information

Tax Exempt Reason:	Tax free export - Goods
Fulfilment Date:	07.06.2023

Invoice #:

Bank Details: No Payment Due

Account Name:

Account No:

Bank Key:

Swift Code:

IBAN:

Payment method:

Registered No: Schwerin HRB 1838

VAT Reg No: DE137437213

Federal ID #:

Registered Address: Honeywell Healthcare Solutions GmbH, Alter Holzhafen 18, Wismar, 23966, Germany

Credit Analyst: Xenia Musat

Sales Rep: Stefan Dreyer

Customer Care Rep: Jessica Wagner +49 3841 360 206

Unless otherwise agreed in writing by the parties, all sales of products and/or services in this document shall be governed solely by the applicable Honeywell Terms and Conditions in effect at the time a Purchase Order is accepted by Honeywell, a copy of which can be found at <https://sps.honeywell.com/us/en/support/safety/legal-documents/sst>. Honeywell's acknowledgment of receipt of a Purchase Order shall not constitute acceptance. By continuing with this transaction, you (Buyer) agree to those Honeywell Terms and Conditions, which are subject to change at Honeywell's discretion without notice. Honeywell expressly limits its acceptance, fulfillment and performance of this Purchase Order to the terms in the Honeywell Terms and Conditions and expressly rejects any different, conflicting or additional terms in the Purchase Order or any other Buyer documents. This sale shall be governed by the Terms and Conditions of the Honeywell legal entity listed on this document.

PRÜFBERICHT – TEST REPORT

Sauerstoffsensoren/Oxygen Sensors OOA, OOI, OOD

Kunde/ Customer	Vandagroph	Retour/ RMA- No.	Kunde/Customer	275 3100 917	Envitec	300264434
Artikel/ Article	000 103-1SC; 000 103VAN	Anzahl/ Quantity	111	Eing.Datum/ Inc.Date	31.05.23	
Bearbeitet/ processed	K. Buer	Prüfdatum/ Insp. Date	07.06.23	Geprüft/ Inspected	Buer	

Nr.	Produkt/ Identification		Messwert/ Test Result				Bewertung/ Evaluation			
	Seriennummer/ Serial no.	Lieferlos/ Manufact. code	Luftwert/ Air signal @ 20,9% O ₂ [mV]	Nullsignal/ Offset @ 0% O ₂ [µV]	Linearität/ Linearity [%]	Bemerkung/ Remark	außerhalb Garantie/ out of warranty	kein Fehler festgestellt/ no failure found	Fehlercode/ Failure- code	Austausch / Replacement
1	111 179	04123	11.5	29	fehlerhaft				2	
2	111 704	11122	0						4	
3										
4										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
16										
17										
18										
19										
20										

Fehler O2-S001: Luftwert außerhalb Toleranz/ Air signal out of tolerance
 Fehler O2-S003: Offset außerhalb Toleranz/ Offset out of tolerance
 Fehler O2-S005: Gehäuse defekt/ Housing defective
 Fehler O2-S007: Sonstiges (unter Angabe in Bemerkung) / Others (see remark)

Fehler O2-S002: Signal instabil / Signal not stable
 Fehler O2-S004: Signal 0mV / Signal 0mV
 Fehler O2-S006: Elektrolyt Austritt / Electrolyte leakage