

Service Repair Sheet SRS68496

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Clare Goodwin

Vet Direct Services Ltd

Technical Support Nurse

0191 2642705

00012824

tech@vet-direct.com

27/Jun/2023

Robert Connor

Viamed

Warranty

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☐

Cleaned by Viamed,
if no declaration certificate
from customer ☐

Signed: _____

Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 22/Jun/2023 Steve Hardaker

22/Jun/2023 Steve Hardaker

Returning an OxiQuant S purchased on invoice RVM141039-1 on 10th Feb 23. Asked her for s/no, as not provided.

Cal down arrow will not allow it to drop below 37.1, so will not calibrate. See video attached.

Replace under warranty.

27/Jun/2023 Robert Connor

Received 1 x OxyQuant S s/n A106095.

Ready For quote

Repair Complete Signed

CC Connor 30.6.23

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35848	Oxygen Analyser	0111275	A106095	Yes

0140050 x 1 FOC
old S/N. SRS, SRN

0111275 x 1 FOC
new S/N, SRS, SRN

UPS x 1 FOC

Service Repair Sheet 68496

Contact Name

Clare Goodwin

Company/ Hospital Name

Vet Direct Services Ltd

Position

Technical Support Nurse

General Phone

0191 2642705

Opera Account

00012824

Email

tech@vet-direct.com

Date Received

27/Jun/2023

Booked in By

Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35848	0111275	A106095	Oxygen Analyser	

Parts Replaced

Time :0 Hour(s)

Qty: 1 0111275

Replaced under warranty with S/N A106300 and sensor A111056.
