

# Service Repair Sheet SRS68502

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Sudath Weeraman

Prime Lanka Associate

9410718732285

00006714

sudathweeraman17@gmail.com

13/Jul/2023

Robert Connor

Viamed

Warranty

## VIAMEDclean

### Goods In Only

Decontamination  
certificate provided  
by customer ☐

Cleaned by Viamed,  
if no declaration certificate  
from customer ☐

Signed: \_\_\_\_\_  
Date: \_\_\_\_\_

### Goods Out Only

Cleaned by Viamed before  
returning to customer

Signed: \_\_\_\_\_  
Date: \_\_\_\_\_

Notes 28/Jun/2023 Kate Griffiths

28/Jun/2023 Kate Griffiths

sending under warranty: MAX-250E, s/n HF29899031 and R-49V s/n V103063. Asked what is wrong with them

13/Jul/2023 Robert Connor

Received 1 x R49V s/n V103063, 1 x MAX-250E s/n HF29899031

Ready For quote

EE

Repair Complete Signed

CGreen 19.7.23

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35926	Oxygen Sensor	0110049	V103063	Yes
SRN35927	Oxygen Sensor	0110429	HF29899031	Yes

0140013 x 1 FOC  
old S/N, SRS, SRN

0110049 x 1  
New S/N, SRS, SRN

0140013 x 1 FOC  
old S/N, SRS, SRN

0110429 x 1 FOC  
New S/N, SRS, SRN

EXIN - send with next Order.





No: 57/8, P.B. Alwis Perera Mawatha, Katubedda  
, Moratuwa, Sri Lanka

071 873 2285

011 262 4324

primelanka07@gmail.com

10 July 2023

The Repair Team.

Viamed Ltd, No.15, Station Road, Cross Hills, Keighley  
West Yorkshire, BD20 7DT  
United Kingdom.

Dear Sir,

The warranty replacement notice, for Oxygen sensor model MAX-250E & R-49V  
Please note below details for your reference.

Model – Oxygen Sensor MAX-250E / R-49V

1. S/N – HF29899031
2. S/N - V103063

Return Reference No. SRS-68502

Thank you,

You're faithfully

S.J. Weeraman

Prime Lanka Associates

No.57/8, P.B. Alwis Perera Mawatha  
Katubadda, Moratuwa  
Sri Lanka.

Service Repair Sheet 68502

Contact Name

Company/ Hospital Name

Direct Phone

Opera Account

Email

Date Received

Booked in By

Sudath Weeraman

Prime Lanka Associate

9410718732285

00006714

sudathweeraman17@gmail.com

13/Jul/2023

Robert Connor

---

Repair	Ref	S/N	Equipment Type
SRN35926	0110049	V103063	Oxygen Sensor

Under Warranty

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110049

Replaced under warranty with S/N V103406

---

Repair	Ref	S/N	Equipment Type
SRN35927	0110429	HF29899031	Oxygen Sensor

Under Warranty

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110429

Replaced under warranty with S/N JC89099020

---