



Peter Bernardes

 CID25456 Opera CID25456 Type:Vandagraph Retail

Peter Bernardes 1 Dunstone Ave, , Plymstock, Devon, PL9 8RH, United Kingdom

Tel **01752 480639** GBP Retail Price List Vandagraph (0010)



Add Issue

Proforma Credit Limit 0.00GBP

 Account Home

 Main Details

Account Memos

Sales History

 Stock
References

🔄 Cust./Supp. Returns

 Service Visits

Distributor Agreements

Documents
Files

 **Linked Issues**

Regulatory Agreements

SRS68513

SRS Created : 10 Jul 2023

Created By Ryan Swaine

Add Watch

[Print Barcodes](#)

[Print A4 Sheet](#)

Split Items into Different SRS Numbers

Upload Document to SRS

Handle with care

Add Items to Supplier Returns Box

Add

☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs

☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

Add Notes

ADD DOCUMENT TO SRS : Document Description	Choose a file to upload: Choose file No file chosen
Next	

Service Repair Sheet 68513				Notes							
Company / Hospital		Peter Bernardes		10/Jul/2023 Ryan Swaine							
Contact Name		Peter Bernardes		10/Jul/2023 Ryan Swaine							
Department				VN202 requires new sensor and check over - Quote if repair required.							
Position				Please give to MG upon arrival							
Company Phone		01752 480639		12/Jul/2023 Robert Connor							
Direct Phone		01752 480639		Received 1 x VN202 s/n VN0222, with blue tee, flow diverter, metal adapter, black plastic case, and R-17VAN s/n 941340.							
Opera Account		CID25456		25/Jul/2023 Catherine Spence							
Email		ptbernardes@blueyonder.co.uk		Engineers room							
Order Number											
Viamed ORD Number											
Date Received Into building		12 Jul 2023									
Type		Quote Before Repair Move to Repair									
Issues?											
Items for Repair											
... ..											
SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)	

SRN35923	Oxygen Analyser VN202			VN0222	VN202	No	No	Unfinished		00:00
SRN35924	Oxygen Sensor Vandagraph	0110217	 1181107	941340	Oxygen sensor R- 17VAN	No	No	Unfinished		00:00

Currently Viewing ITEM **SRN35923 Oxygen Sensor Vandagraph 0110217 941340 Oxygen sensor R-17VAN**

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Non Supplied	Non added Yet	Non added Yet

+