



Jim Veitch

CID25767 Opera CID25767 Type:Vandagraph Retail
Jim Veitch 2 Skylands Rise, , Hamilton, , ML3 8TS, United Kingdom
Tel 07810396917 GBP Retail Price List Vandagraph (0010) Log Call Add Issue
Proforma Credit Limit 0.00GBP

- Account Home
- Main Details
- Account Memos
- Sales History
- Stock References
- Cust./Supp. Returns
- Service Visits
- Distributor Agreements
- Documents Files
- Linked Issues
- Regulatory Agreements

SRS68535

SRS Created : 04 Aug 2023
Created By Ryan Swaine
Add Watch

Print Barcodes
Print A4 Sheet
Split Items into Different SRS Numbers

Handle with care

Add Items to Supplier Returns Box

Add

☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs

☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

Add Notes

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description

Choose a file to upload: Choose file No file chosen

Next

Service Repair Sheet 68535				Notes							
Company / Hospital		Jim Veitch		04/Aug/2023 Ryan Swaine							
Contact Name		Jim Veitch		04/Aug/2023 Ryan Swaine							
Department				TEK-OX sn. TX0137, not turning on. To test and quote for repair. Please give to MG upon arrival.							
Position				09/Aug/2023 Robert Connor							
Company Phone		07810396917		Received 1 x tek-ox s/n TX0137, with yellow case, and blue tee.							
Direct Phone		07810396917		09/Aug/2023 Catherine Spence							
Opera Account		CID25767		in engineers room							
Email		firefox996@hotmail.co.uk									
Order Number											
Viamed ORD Number											
Date Received Into building		09 Aug 2023									
Type		Quote Before Repair Move to Repair									
Issues?											

Items for Repair										
...										
SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN35958	Oxygen Analyser	9712000	 232767	TX0137	Tex-Ox Cable Ass	No	No	Unfinished		00:00

14/08/2023, 10:33

SRS View

TEK-OX									
SRN35958 Engineer Notes: INTERNAL NOTES not for customer discussion 11/Aug/2023 Michael Green The Tek-Ox analyser has been tested. The battery door battery contact should be replaced. The R-17VAN (J8) Oxygen sensor has no output. 11/Aug/2023 Michael Green No batteries were supplied.									

Currently Viewing ITEM SRN35958 Oxygen Analyser TEK-OX 9712000 TX0137 Tex-Ox Cable Ass

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Non Supplied	11/Aug/2023 Michael Green The Tek-Ox analyser has been tested. The battery door battery contact should be replaced. The R-17VAN (J8) Oxygen sensor has no output. 11/Aug/2023 Michael Green No batteries were supplied.	Non added Yet

-