

Service Repair Sheet SRS68545

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Amanda Perry

Vet Direct Services Ltd

Purchasing Manager

0191 2642705

0191 2642705

00012824

repairs@vet-direct.com

10/Aug/2023

Robert Connor

Viamed

Warranty

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☐

Cleaned by Viamed,
if no declaration certificate
from customer ☒

Signed: RE
Date: 10/08/23

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____
Date: _____

Notes 10/Aug/2023 Robert Connor

10/Aug/2023 Robert Connor

Received 1 x OsiQuant S s/n A106286, with OOI103 s/n A111042, flow diverter, oxygen stem, and blue tee.

10/Aug/2023 Robert Connor

Customer reports unit not reading lower than 45% in air.

Ready For quote

Repair Complete Signed

EC Green 14-8-23

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35963	Oxygen Analyser	0111275	A106286	Yes
SRN35964	Oxygen Sensor	0110660	A111042	Yes

3 Part of ser unit.

0140050 x 1 FOC

S/N: of unit + oxygen sensor, SRS, SEN

0111275 x 1 FOC

S/N of New unit and oxygen sensor, SRS, SEN

Warranty Replacement

UPS x 1 FOC

Equipment for Repair

Repair Reference – 18664

Date: 8/8/23
To: VIANEN

Vet Direct
Units 9 & 10, Gateway West
Newburn Riverside
Newcastle upon Tyne
NE15 8NZ

Tel: 0191 2642705
Email: repairs@vet-direct.com

The enclosed product has been sent to you for inspection. Please provide estimate to repair – please send estimate to repairs@vet-direct.com

Product:	ENVITEC OXIGENANT 5 OXYGEN ANALYSOR		
Serial No:	ID: 2250782		
Accessories:	—		
Quantity:	1		
Condition:	USED		
Work required:	WHEN CALIBRATING WON'T GO LOWER THAN 45.2		
Warranty:	<input checked="" type="radio"/> Yes /	No 02/05/23	PO Number: 125474
Quotation required?	Yes /	No	

Service Repair Sheet 68545

Contact Name	Amanda Perry
Company/ Hospital Name	Vet Direct Services Ltd
Position	Purchasing Manager
Direct Phone	0191 2642705
General Phone	0191 2642705
Opera Account	00012824
Email	repairs@vet-direct.com
Date Received	10/Aug/2023
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35963	0111275	A106286	Oxygen Analyser	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0111275

Replaced under warranty with S/N A106347 which includes sensor S/N A111136

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35964	0110660	A111042	Oxygen Sensor	

Time :0 Hour(s)

Replaced under warranty with S/N A106347 which includes sensor S/N A111136
