Service Repair Sheet SRS68532

Contact Name

Company/ Hospital Name

Department

Position Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Andrew Kelly

Whiston Hospital

Medical Engineering

Senior Medical Engineer / Deputy

01512904294

01514261600

00002152

Andrew.Kelly@sthk.nhs.uk

08/Aug/2023

Robert Connor

Viamed

Warranty

VIAMEDCIO Goods In Only	ean
Decontamination certificate provided by customer	
Cleaned by Vianged, if no declaration certificate from customer Signed: Date:	
Goods Out Only	
Cleaned by Viamed be returning to customer	fore
Signed:	

Notes 31/Jul/2023 Kate Griffiths 31/Jul/2023 Kate Griffiths R-48V s/n V103408 failed under warranty 31/Jul/2023 Steve Hardaker

Sold on 23/8/22, CVM138828. These were 2 years old when supplied (Date code 2020-09-01), so SN has agreed to swap

08/Aug/2023 Robert Connor

Received 1 x R-48v s/n V103408.

Ready For quote

Repair Complete Signed

14.8.23

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35939	Oxygen Sensor	0110048	V103408	Yes

0140013 × 1 FOC 010 S/N, ses, sen

0110048 × 1 FOC New SIN, SES, SEN warranty leplacement UPS × 1 FOC

St Helens and Knowsley Teaching Hospitals Wills

University Clinical Education Centre

Medical Engineering,
Whiston Hospital,
Prescot,
Merseyside,
L35 5DR

0151 430 1273 andrew.kelly@sthk.nhs.uk

03/08/2023

Viamed Limited, 15 Station Road, Cross Hills, Keighley, West Yorkshire, BD20 7DT

REF: SRS68532

Dear Steve,

Please find enclosed 1 x Viamed R-48v cell (sr/noV103408). The cells are returned under Ref: SRS68532. I would like to return under warranty for replacement as discussed via email.

Regards,

Andrew Kelly (Deputy Manager Medical Engineering) Service Repair Sheet 68532

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Date Received

Booked in By

Andrew Kelly

Whiston Hospital

Medical Engineering

Senior Medical Engineer / Deputy Manager

01512904294

01514261600

00002152

Andrew.Kelly@sthk.nhs.uk

08/Aug/2023

Robert Connor

Repair

Ref

S/N 0110048 V103408 **Equipment Type**

Oxygen Sensor

Under Warranty

Time :0 Hour(s)

Parts Replaced

SRN35939

Qty: 1

0110579

Replaced under warranty with S/N A100943