

# Service Repair Sheet SRS68533

Contact Name

Richard Quigley

Company/ Hospital Name

Brennan & Co NI

Department

Position

Direct Phone

General Phone

0289 0410136

Opera Account

00012907

Email

rquigley@smcni.com

Order Number

Date Received

09/Aug/2023

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Quote

**VIAMEDclean**

**Goods In Only**

Decontamination  
certificate provided  
by customer

Cleaned by Viamed,  
if no declaration certificate  
from customer

Signed: Re  
Date: 9/8/23

**Goods Out Only**

Cleaned by Viamed before  
returning to customer

Signed: \_\_\_\_\_  
Date: \_\_\_\_\_

Notes 31/Jul/2023 Ryan Swaine

31/Jul/2023 Ryan Swaine

MAXO2 ME - displaying fault code, has tried a new sensor, maybe the cable?

03/Aug/2023 Ryan Swaine

add calibration pn. 0180020 GBP £30 to repair quotation.

09/Aug/2023 Robert Connor

1 x MAXO2ME s/n FA75699022, coiled cable s/n 1454195, 4 x AA battery, 2 x MAX550E s/n HH65699183, HM500990  
x flow diverter

Ready For quote

CCreen 15 10-8-23

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35954	Oxygen Monitor	0111263	FA75699022	<u>N</u>
SRN35955	Oxygen Monitor Cable	0131700	Tracking7	<u>N</u>
SRN35956	Oxygen Sensor	0110452	HH65699183	Yes
SRN35957	Oxygen Sensor	0110452	HM50099074	Yes

Part of s  
unit. gr

0131700 x 1 @ £21.25.  
S/N, SRS, SRN

0140050 x 1/4 hr @ £90 per hour  
S/N, SRS, SRN.

only add S/N: FA75699  
SEN 35954-35955  
CG 17-8-23.

0131700 x 1 @ £30.70.  
0140025 x 1  
0131700 x 1  
old S/N

UPS x 1 @ £12.