

Ryan Swaine [Required Reading](#) 10 Issues | [My Requests 19.00 °C](#)

Contacts

Search

Keltic Seafare

CID21505 Opera CID21505 Type:Vandagraph Retail

Keltic Seafare c/o Alasdair Hughson, Unit 6, Strathpeffer Road Ind. Estate, Dingwall, , IV15 9SP, United Kingdom

Tel **07801 659618** GBP Retail Price List Vandagraph (0010)

Log Call

Add Issue

Proforma Credit Limit 0.00GBP

Account Home

Main Details

Account Memos

Sales History

Stock References

Cust./Supp. Returns

Service Visits

Distributor Agreements

Documents Files

Linked Issues

Regulatory Agreements

SRS68540

SRS Created : 09 Aug 2023
Created By Robert Connor
Add Watch

[Print Barcodes](#)
[Print A4 Sheet](#)
[Split Items into Different SRS Numbers](#)

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description

Choose a file to upload:

Choose file

No file chosen

Next

Handle with care

Add Items to Supplier Returns Box

Add

☐ Return for Credit / Return to Stock

Unopened - will apply to all items on srs

☐ Clear From System - Force from System.

- will apply to all items on srs

Add notes to SRS

Add Notes

Service Repair Sheet 68540		Notes
Company / Hospital	Keltic Seafare	09/Aug/2023 Robert Connor
Contact Name	Alasdair Hughson	09/Aug/2023 Robert Connor
Department		Received 4 x VN202 /sn VN2889, VN3005 with battery, 00107, VN3004 with battery.
Position		09/Aug/2023 Catherine Spence
Company Phone	07801 659618	in engineers room
Direct Phone	07801 659618	
Opera Account	CID21505	
Email	clams1@icloud.com	
Order Number		
Viamed ORD Number		
Date Received Into building	09 Aug 2023	
Type	Quote Before Repair Move to Repair	
Issues?		

Items for Repair

.....

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
-----	-----------	-----------------	---------	--------------	-------------	--------------	-----------------	--------	-------------	------------

https://www.vmsecure.me.uk/intranet/databases/repairs/viewrepair2.php?zz=1&A=&vui=13&user=Ryan Swaine&idp=raxYXanx9ACow&mph=&se... 1/2

SRN35942	Oxygen Analyser VN202	7900100	 502899	00107	Oxygen Analyser VN202 Mk2	No	No	Unfinished		00:00
SRN35942 Engineer Notes: INTERNAL NOTES not for customer discussion 25/Aug/2023 Michael Green The VN202 Mk2 analyser has been tested. The unit is working as expected. The sensor cable is over stretched, but works as expected.										
SRN35943	Oxygen Analyser VN202			VN2889	VN202	No	No	Unfinished		00:00
SRN35943 Engineer Notes: INTERNAL NOTES not for customer discussion 25/Aug/2023 Michael Green The VN202 analyser has been tested. The unit is working as expected.										
SRN35944	Oxygen Analyser VN202			VN3004	VN202	No	No	Unfinished		00:00
SRN35944 Engineer Notes: INTERNAL NOTES not for customer discussion 25/Aug/2023 Michael Green The VN202 analyser has been tested. The unit has a minus reading when a sensor is connected. The cable connector has flat spots where the sensor fails to read. The unit needs an adjustment to the zero point.										
SRN35945	Oxygen Analyser VN202			VN3005	VN202	No	No	Unfinished		00:00
SRN35945 Engineer Notes: INTERNAL NOTES not for customer discussion 25/Aug/2023 Michael Green The VN202 analyser has been tested. The cable connector has flat spots where the sensor fails to read. The unit needs an adjustment to the zero point.										

Currently Viewing ITEM SRN35942 Oxygen Analyser VN202 VN3005 VN202

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Non Supplied	25/Aug/2023 Michael Green The VN202 analyser has been tested. The cable connector has flat spots where the sensor fails to read. The unit needs an adjustment to the zero point.	Non added Yet

-