

Service Repair Sheet SRS68551

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Vandenabeele NV

0032 51311812

0032 51331508

00007716

info@vandenabeele.be

CVM142158

06/Sep/2023

Robert Connor

Viamed

Warranty

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☒

Cleaned by Viamed,
if no declaration certificate
from customer ☐

Signed: _____

Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 22/Aug/2023 Aqib Majeed

22/Aug/2023 Aqib Majeed

customer wanting to return 7 x faulty R-17A oxygen sensors.

These are the serial numbers:

778250

778249

778257

778254

778266

778268

778253

06/Sep/2023 Robert Connor

Received 7 x R17A s/n 778249, 778250, 778253, 778254, 778266, 778268, 778271.

Ready For quote

Repair Complete Signed

CGreen 7.9.23

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35979	Oxygen Sensor	0110117	778249	Yes
SRN35980	Oxygen Sensor	0110117	778250	Yes
SRN35981	Oxygen Sensor	0110117	778253	Yes
SRN35982	Oxygen Sensor	0110117	778254	Yes
SRN35983	Oxygen Sensor	0110117	778266	Yes
SRN35984	Oxygen Sensor	0110117	778268	Yes
SRN35985	Oxygen Sensor	0110117	778271	Yes

0014 0013 x 7 FOC
old S/N, SRS, SRN

0110117 x 7 FOC
new S/N's, SRS, SRN

UPS x 1 FOC.

KBC	IBAN	BE81 4649 1092 4124
	BIC	KREDBEBB
ING	IBAN	BE45 3850 0329 0989
	BIC	BBRUBEBB



- Elektrisch- en handgereedschap
- Werkkledij en -schoenen
- Reiniging & veiligheid
- Stroomgroepen & pompelpompen
- Elektromotoren
- Mobiele telecom oplossingen
- Telefooncentrales & Internet
- ICT & Cloud oplossingen
- Track&Trace
- GPS navigatie
- Mobiele audio - video

VERZENDNOTA

Klant: 220874

Bin. 1

Zendnotanummer: 23/0041612 23/0040674
te vermelden bij eventuele klacht

CV 13:13:10

Om te kunnen aanvaard worden, dienen klachten te worden ingediend binnen 10 kalenderdagen na factuurdatum.
De geleverde goederen blijven ons eigendom tot na volledige betaling.
De algemene verkoopsvoorwaarden zijn te consulteren op onze website.
De persoonlijke gegevens op dit document zijn bestemd voor intern gebruik en promotieacties van onze onderneming.
Overeenkomstig de wet voor bescherming van de privacy heeft de klant het recht de gegevens in te zien en zo nodig te wijzigen.

Betalingsvoorwaarde: 1

Kontant



Service Repair Sheet 68551
Company/ Hospital Name Vandenabeele NV
Direct Phone 0032 51311812
General Phone 0032 51331508
Opera Account 00007716
Email info@vandenabeele.be
Order Number CVM142158
Date Received 06/Sep/2023
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35979	0110117	778249	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110117

Replaced under warranty with S/N 851750

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35980	0110117	778250	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110117

Replaced under warranty with S/N 851751

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35981	0110117	778253	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110117

Replaced under warranty with S/N 851752

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35982	0110117	778254	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110117

Replaced under warranty with S/N 851753

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35983	0110117	778266	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110117

Replaced under warranty with S/N 851754

Service Repair Sheet 68551
Company/ Hospital Name Vandenabeele NV
Direct Phone 0032 51311812
General Phone 0032 51331508
Opera Account 00007716
Email info@vandenabeele.be
Order Number CVM142158
Date Received 06/Sep/2023
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35984	0110117	778268	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110117

Replaced under warranty with S/N 851755

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35985	0110117	778271	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110117

Replaced under warranty with S/N 880743
