

## Service Repair Sheet 68533

Contact Name	Richard Quigley
Company/ Hospital Name	Brennan & Co NI
General Phone	0289 0410136
Opera Account	00012907
Email	rquigley@smcni.com
Order Number	SD1233
Date Received	09/Aug/2023
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN35954	0111263	FA75699022	Oxygen Monitor	No Fault Found Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	
SRN35955	0131700	Tracking7	Oxygen Monitor Cable	Complete - Repaired Time :0 Hour(s)

## Parts Replaced

Qty: 1 0131700

Replaced with Cable Tracking Number 16

Repair	Ref	S/N	Equipment Type		Under Warranty
SRN35956	0110452	HH65699183	Oxygen Sensor	No Fault Found Time :0 Hour(s)	

No fault found.

Repair	Ref	S/N	Equipment Type		Under Warranty
SRN35957	0110452	HM50099074	Oxygen Sensor	No Fault Found Time :0 Hour(s)	

No fault found.