

DL Full, HL Full



Honeywell Healthcare Solutions GmbH

✓CID4348 Opera 00007282 Type:Company Supplier Customer
 Honeywell Healthcare Solutions GmbH Alter Holzhafen 18, Wismar,
 , D-23966, Germany
 Tel 0049 3841 360204 Euro Distributor (0004)

Add Issue

VAT DE137437213

Account Home	Main Details	Account Memos	Sales History	Purchase Orders	Supplier Returns	Stock References	Cust/Supp. Returns	Service Visits
Distributor Agreements	Documents Files	Linked Issues	Regulatory Agreements					

MHRA Registration number: 29372

BOX:930

Manufacturer RMA : 300267776

☒ Repaired ☐ No Fault Found

Returned Barcode

Close File 930

Tick All Replaced

Review	Stock Ref	Sup Ref	B/C	S/N	Fault	Replaced	No Fault Found	Repaired	Credited	Out Warranty	Returned Unrepaired	Notes
			2164602	JJ143171	No Fault Found Country of Origin: Germany Customs Value: 5.00 euro	☐	☐	☐	☒	☐	☐	
			2082923	210146738	Unstable Output Signal Country of Origin: Germany Customs Value: 5.00 euro	☐	☐	☐	☒	☐	☐	
			2153462	301148469	Low Output Country of Origin: Germany Customs Value: 5.00 euro	☐	☐	☐	☒	☐	☐	
			2153491	301148498	Low Output Country of Origin: Germany Customs Value: 5.00 euro	☐	☐	☐	☒	☐	☐	
			2153552	301148559	Low Output Country of Origin: Germany Customs Value: 5.00 euro	☐	☐	☐	☒	☐	☐	

					5.00 euro							
Last Rev Sep 23 8010006 Customer Stats	8010006		2197149	304149902	Unstable Output Signal Country of Origin: Germany Customs Value: 5.00 euro	☐	☐	☐	☒	☐	☐	

Update Returns

Customer Failure Statistics

Start From 28/09/2021 End at 28/09/2023

Invoice Correction 5264791685**ORIGINAL**

Invoice Correction Date: 22.09.2023

Honeywell Healthcare Solutions GmbH

Alter Holzhafen 18

Purchase Order No: RTS3100930

23966 Wismar

Germany

Billed to: 1797448
 Vandagraph Sensor Technologies Ltd.
 15 Station Road
 Cross Hills, West Yorkshire
 KEIGHLEY
 BD20 7DT
 United Kingdom

Sold to: 1797448
 Vandagraph Sensor Technologies Ltd.
 15 Station Road
 Cross Hills, West Yorkshire
 KEIGHLEY
 BD20 7DT
 United Kingdom

Order Information:
 Credit Memo Request: 64137876
 Sales Office: 2170 DE SPS Wismar
 Incoterms: FCA Origin
 Payment Terms: Net 30 Days After Invoice Date

Ship to: 1797448
 Vandagraph Sensor Technologies Ltd.
 15 Station Road
 Cross Hills, West Yorkshire
 KEIGHLEY
 BD20 7DT
 United Kingdom

EM NO.	Material No.	QTY	UOM	UNIT PRICE	EXT. PRICE	VAT %
00010	E1001721 Oxygen Sensor OOD103-2V Customer Part Nbr: 8010004 credit note for SN:143171 ✓	1 ✓	EA	28,63 ✓	-28,63	0%
00020	E1002733 Oxygen Sensor OOD103 VAN 8010006 Customer Part Nbr: 8010006 Credit note for SN: 146738 ✓ 148469 ✓ 149498 ✓ 148559 ✓ 149902 ✓	5 ✓	EA	21,74	-108,70	0%

Should be
99.77 €

Ins #:

Link Details: No Payment Due

Account Name:

Account No:

Bank Key:

Swift Code:

AN:

Payment method:

Registered No: Schwerin HRB 1838

VAT Reg No: DE137437213

Federal ID #:

Registered Address: Honeywell Healthcare Solutions GmbH, Alter Holzhafen 18, Wismar, 23966, Germany

Credit Analyst: Xenia Musat

Sales Rep: Stefan Dreyer

Customer Care Rep: Jessica Wagner +49 3841 360 206

Unless otherwise agreed in writing by the parties, all sales of products and/or services in this document shall be governed solely by the applicable Honeywell Terms and Conditions in effect at the time a Purchase Order is accepted by Honeywell, a copy of which can be found at <https://sps.honeywell.com/us/en/support/safety/legal-documents/sst>. Honeywell's acknowledgment of receipt of a Purchase Order shall not constitute acceptance. By continuing with this transaction, you (Buyer) agree to those Honeywell Terms and Conditions, which are subject to change at Honeywell's discretion without notice. Honeywell expressly limits its acceptance, fulfillment and performance of this Purchase Order to the terms in the Honeywell Terms and Conditions and expressly rejects any different, conflicting or additional terms in the Purchase Order or any other Buyer documents. This sale shall be governed by the Terms and Conditions of the Honeywell legal entity listed on this document.

Invoice Correction 5264791685

ORIGINAL

Invoice Correction Date: 22.09.2023

Honeywell Healthcare Solutions GmbH

Purchase Order No: RTS3100930

Alter Holzhafen 18

23966 Wismar

Germany

EM NO.	Material No.	QTY	UOM	UNIT PRICE	EXT. PRICE	VAT %
--------	--------------	-----	-----	------------	------------	-------

Totals

Total Before VAT -137,33 EUR

VAT-Total 0,00 EUR

Total Amount -137,33 EUR

Tax Information

Tax Exempt Reason: Tax free export - Goods

Fulfilment Date: 22.09.2023

Integrity and Compliance at Honeywell

Honeywell places the highest value on the integrity of its business operations. We expect our employees and business partners to comply with our Code of Business Conduct and all applicable laws and regulations. If you become aware of illegal or improper conduct by a Honeywell employee please contact your Honeywell relationship manager. You can also report misconduct directly to us either via e-mail to our Integrity and Compliance Office at access.integrity.helpline@honeywell.com or via our Access helpline accessible worldwide at 800-237-5982.

MS #:

Registered No: Schwerin HRB 1838 VAT Reg No: DE137437213 Federal ID #:

Registered Address: Honeywell Healthcare Solutions GmbH, Alter Holzhafen 18, Wismar, 23966, Germany

PRÜFBERICHT – TEST REPORT

Sauerstoffsensoren/Oxygen Sensors OOA, OOI, OOD

ENVITEC
by Honeywell

Kunde/ Customer	Vandagroph	Retour/ RMA- No.	Kunde/Customer PTS 3100930	Envitec 300267776
Artikel/ Article	OOD103i 000103-2V	Anzahl/ Quantity	511	Eing.Datum/ Inc.Date 14.09.23
Bearbeitet/ processed	K. B. M. U.	Prüfdatum/ Insp. Date	21.09.23	Geprüft/ Inspected B. M. U.

Produkt/ Identification		Messwert/ Test Result				Bewertung/ Evaluation				
Nr.	Seriennummer/ Serial no.	Lieferlos/ Manufact. code	Luftwert/ Air signal @ 20,9% O ₂ [mV]	Nullsignal/ Offset @ 0% O ₂ [µV]	Linearität/ Linearity [%]	Bemerkung/ Remark	außerhalb Garantie/ out of warranty	kein Fehler festgestellt/ no failure found	Fehlerkode/ Failure- code	Austausch / Replacement
1	146378	09122	0						4	
2	148469	01123	0						4	
3	148498	01123	0						4	
4	148559	01123	0						4	
5	148902	04123	11,2	32	1,0			X		
6	143171	02123	10,9	35	1,0			X		
7										
8										
9										
10										
11										
12										
13										
14										
15										
16										
17										
18										
19										
20										

Fehler O2-S001: Luftwert außerhalb Toleranz/ Air signal out of tolerance

Fehler O2-S003: Offset außerhalb Toleranz/ Offset out of tolerance

Fehler O2-S005: Gehäuse defekt/ Housing defective

Fehler O2-S007: Sonstiges (unter Angabe in Bemerkung) / Others (see remark)

Fehler O2-S002: Signal instabil / Signal not stable

Fehler O2-S004: Signal 0mV / Signal 0mV

Fehler O2-S006: Elektrolyt Austritt / Electrolyte leakage