

Service Repair Sheet SRS68585

Contact Name
Company/ Hospital Name
Department
Position
Direct Phone
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By
Main Company
Type Return

Oskar Slechta
Chromservis s.r.o

Senior Internal Sales Advisor
420274021221
420274021211
00012607
o.slechta@chromservis.eu

09/Oct/2023
Robert Connor
Viamed
Warranty

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer

☐

Cleaned by Viamed
if no declaration certificate
from customer

☐

Signed: _____

Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 27/Sep/2023 Kate Griffiths

27/Sep/2023 Kate Griffiths

Sending in R-22A, s/n 919838 under warranty. ``After installation, the value was 3mV only``

09/Oct/2023 Robert Connor

Received 1 x R22A s/n 919838

Ready For quote

Repair Complete Signed

CGNORON 11-10-23

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36061	Oxygen Sensor	0110122	919838	Yes

0140013 x 1 FOC
old S/N, SRS, SRN

0110122 x 1 FOC
New S/N, SRS, SRN

UPS x 1 FOC

Ref: SRS68585

To attn. Kate Griffiths
Viamed Ltd.

Prague, October 2nd., 2023

Dear Kate,

after our E-mailing, we are sending you to back **1x R-22A sensor, s/n 919838**.
The sensor doesn't work, it isn't possible to calibrate it. After installation, the value is 3mV only. I would like to ask you for replacement under warranty, if it is possible.

Thanks so much,
best regards


Oskar Slechta
Chromservis Czech

Service Repair Sheet 68585

Contact Name	Oskar Slechta
Company/ Hospital Name	Chromservis s.r.o
Position	Senior Internal Sales Advisor
Direct Phone	420274021221
General Phone	420274021211
Opera Account	00012607
Email	o.slechta@chromservis.eu
Date Received	09/Oct/2023
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN36061	0110122	919838	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110122

Replaced under warranty with S/N 984877
