

# Service Repair Sheet SRS68592

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Janice Hunter

Hunter and Co

Accounts

01383852049

01383852049

00020062

hunterandco@outlook.com

04/Oct/2023

Robert Connor

Viamed

Bring To Attention

## VIAMEDclean

### Goods In Only

Decontamination  
certificate provided  
by customer ☐

Cleaned by Viamed,  
if no declaration certificate  
from customer ☐

Signed: \_\_\_\_\_

Date: \_\_\_\_\_

### Goods Out Only

Cleaned by Viamed before  
returning to customer

Signed: \_\_\_\_\_

Date: \_\_\_\_\_

Notes 04/Oct/2023 Robert Connor

04/Oct/2023 Robert Connor

Returned 1 x R-22A s/n 931337, originally invoiced to Envirogen.

Ready For quote

Repair Complete Signed

CCNeen 12.10.23

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36059	Oxygen Sensor	0110122	931337	Yes <u>NO</u>

0140015 x 1 FCC

SIN, SRS, SRN

Returning not replaced

AS requested by ~~the~~ Hunter and Co.

To be shipped direct to their customer

UPS x 1 FCC.

Return Address  
Please see  
SRS on system  
CG 12.10.23.

Service Repair Sheet 68592

Contact Name

Janice Hunter

Company/ Hospital Name

Hunter and Co

Department

Accounts

Direct Phone

01383852049

General Phone

01383852049

Opera Account

00020062

Email

hunterandco@outlook.com

Date Received

04/Oct/2023

Booked in By

Robert Connor

---

Repair

Ref

S/N

Equipment Type

SRN36059

0110122

931337

Oxygen Sensor

Return Unrepaired

Time :0 Hour(s)

---