

Service Repair Sheet 68588

Contact Name	Andrea Pierfederici
Company/ Hospital Name	ASD Blue Shark Diving 2
Direct Phone	+39 339.5314956
General Phone	009 3395314956
Opera Account	CID23637
Email	andpierf@gmail.com
Date Received	17/Oct/2023
Booked in By	Robert Connor

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN36072	7910110	03281	Oxygen Analyser VN202	Complete - Repaired Time :0.5 Hour(s)

The VN202 analyser has been repaired under warranty. The sensor input connector has been rewired.

---

Repair	Ref	S/N	Equipment Type	
SRN36073	0131203	0002107	Oxygen Monitor Cable	No Fault Found Time :0 Hour(s)

The sensor cable has been tested. No fault was found.

---

Repair	Ref	S/N	Equipment Type	
SRN36074	0131203	0002138	Oxygen Monitor Cable	No Fault Found Time :0 Hour(s)

The sensor cable has been tested. No fault was found.

---