

PC Full, EH Full



Sebastian Zagrodzki

 CID21123 Opera CID21123 Type: **Vandagraph Retail**
Sebastian Zagrodzki Farbstrasse 9, , 8800 Thalwil, Switzerland
 Tel GBP Retail Price List Vandagraph (0010) 

Add Issue

Proforma Credit Limit 0.00GBP



 Account Home

 Main Details

Account Memos

 Sales History

Stock References

[Cust./Supp. Returns](#)

 Service
Visits

Distributor Agreements

Documents
Files

 **Linked Issues**

Regulatory Agreements

SRS68591

SRS Created : 04 Oct 2023

Created By Ryan Swaine

Add Watch

[Print Barcodes](#)

[Print A4 Sheet](#)

Split Items into Different SRS Numbers

Upload Document to SRS

ADD
DOCUMENT
TO SRS :
Document
Description

Choose a file to upload: No file chosen

Next

Handle with care

Add Items to Supplier Returns Box

Add

☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs

☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

Add Notes

Service Repair Sheet 68591		Notes
SELECT * FROM viamedquoteaddress where ID='21123'		04/Oct/2023 Ryan Swaine
Company / Hospital	Sebastian Zagrodzki	04/Oct/2023 Ryan Swaine TEK-OX sn: TX3137, only turns on when it is tapped against the palm of your hand. 17/Oct/2023 Robert Connor Received 1 x tek-ox s/n TX 3137, with flow diverter
Contact Name	Sebastian Zagrodzki	
Department		
Position		
Company Phone		
Direct Phone	0797230196	LINKED ISSUE NOTES: 309865: AutoGenerated Issue SRS68591 Appears to be Complete
Opera Account	CID21123	
Email	sebek@zagrodzki.net	
Order Number		
Viamed ORD Number		
Date Received Into building	17 Oct 2023	
Type	Repair Approved	
Issues?	309865	

Items for Repair

...

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN36075	Vandagraph Tek Ox	7910211 Requires Service Manual Linking in System	 1389531	TX3137	Oxygen Analyser Tek-Ox	No	No	Complete - Repaired 18 Oct 2023 Michael Green	Battery Leak	00:00
SRN36075 Engineer Notes: INTERNAL NOTES not for customer discussion 18/Oct/2023 Michael Green The Tek-Ox analyser has been repaired. The battery door and contact have been replaced. New batteries have been fitted.										

Currently Viewing ITEM SRN36075 Vandagraph Tek Ox 7910211 TX3137 Oxygen Analyser Tek-Ox

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The Tek-Ox analyser has been repaired. The battery door and contact have been replaced. New batteries have been fitted.	18/Oct/2023 Michael Green The Tek-Ox analyser has been repaired. The battery door and contact have been replaced. New batteries have been fitted.	The Tek-Ox analyser has been repaired. The battery door and contact have been replaced. New batteries have been fitted.

-