Service Repair Sheet SRS68602

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Wee Chew

Kingston Hospital NHS Trust

Clinical Engineering Clinical Engineer

020 89342392

00002421

Wee.Chew@nhs.net

18/Oct/2023

Robert Connor

Viamed

Quote

	VIAMEDclean
	Goods In Only
	Decontamination /
	certificate provided
ı	by customer
f	Cleaned by Viamed, fino declaration certificate from customer Signed: Date: 18/15/23
(Goods Out Only
(Cleaned by Viamed before
r	eturning to customer
4	Signed:
	Date:

Notes 16/Oct/2023 Steve Hardaker 16/Oct/2023 Steve Hardaker

Is returning a Microstim DB3 for fixed cost repair, the sounder isn t working even on the Microstim tester. He traced this to a faulty chip U2. Have emailed cost of £60+VAT and SRS details, will update with s/n if he responds with it.

16/Oct/2023 Steve Hardaker

s/n H0003048.

18/Oct/2023 Robert Connor

Received 1 x DB3 s/n H0003048, with battery.

Ready For quote

careen 20.10.23

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36096	Microstim DB3	2510000	H0003048	2

2540010 × 1 @ £ 60 SIN, SRS, SRN



DOCUMENTS ENCLOSED

Returns Ref: Ret SRS68602

Job No: 319734

VIAMED LTD - UK01291765-01

15 Station Road Cross Hills KEIGHLEY West Yorkshire

ENGLAND

BD20 7DT

Clinical Engineering Galsworthy Road Kingston upon Thames Surrey KT2 7QB Tel: 0208-934-2391/2

Fax: 0208-934-6435

Date: 16.10.2023

Please find enclosed the following equipment:

EQ No

108408

SERIAL No

H0003048

MANUFACTURER

Viamed

EQUIPMENT Nerve Stimulator MODEL

Microstim DB3

Fault: No audio output

The enclosed device or parts have been and are classed as decontaminated as per our Hospital Policy

The above items are subject to our order (PO for £60.00 Fixed Price will be arrange & send ASAP)

Please Note:-. We have removed all patient data, however, in the event that there is data stored that has not been removed please ensure that this is treated with confidence and the storage is destroyed as required. In the event that you need to return the storage part please return this to us and we will destroy this.

I would be obliged if you would give this your immediate attention and return to the Clinical Engineering Department.

Invoices should be addressed to the Clinical Engineering Department at the same address. Yours faithfully,

Wee Chew (wee.chew@nhs.net)

② ② ② □ □ ② ∨ ② □ □ Catherine Spence Required Reading 1 Calls 37 Issues 26 Unread 24 ISO Tasks | My Requests 18.00 °C Stock Stock Search

Stock Search

Search

Stock Stock Search

Search

Stock Stock Search

Search

Stock Stock Search

Search

Stock Stock Search

Stock Stock Search

Search

Stock Search

Stock Search

Stock Search

Stock Search

Stock Search

Stock Search

Search


Search


Stock Searc

ML Full, EH Full



































CID4307 Opera 00002421 Type:NHS Hospital End User

Kingston Hospital NHS Trust EME Department, Galsworthy Road, Kingston upon Thames, , UK Tel GBP End User (0001) Log Call

Add Issue

Credit Limit 0.00GBP



Use:0001 GBP End User

Repair SRS68602 Values in Pounds @ 1: 1.00

SRN36096	Microstim DB3	2510000			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		2540010	1	£60.00	£60.00
				Parts Cost	£60.00

Page updated, TRipple check prices to price in intrastats main search

CHECK PRICES BEFORE SENDING QUOTE

Quote Sent