Service Repair Sheet SRS68608

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Amanda Perry

Vet Direct Services Ltd

Purchasing Manager

0191 2642705

0191 2642705

00012824

Amanda.Perry@vet-direct.com

18/Oct/2023

Robert Connor

Viamed

Bring To Attentention

VIAMEI Goods In O Decontaminati certificate prov by customer	nly on	
Cleaned by Vi if no declaration of from customer Signed:	amed, ertificate RC	V 1/23
Goods Out Cleaned by V returning to co	iamed b	pefore

Date: _

Notes 18/Oct/2023 Robert Connor 18/Oct/2023 Robert Connor

Returned 1 x OxiQuant S s/n A106091, with OOM111 s/n A110790, flow diverter, blue tee, and oxygen stem. Need to contact customer and establish why the unit was returned.

Ready For quote

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36097	Oxygen Analyser	0111275	A106091	Yes
	Oxygen Sensor		A110790	Yes

) Part of comple

0140050 × 1 FOC 01d A106091 (A110790 oxygen sensor) ses, sen

0111275 × 1 FOC New SIN: A106408 (A111197) Dxygen Sensor) SRS, SRN × 1 FC

Equipment for Repair

Date: 9/10/23
To: VIA ~~~

Repair Reference - 23104

Vet Direct
Units 9 & 10, Gateway West
Newburn Riverside
Newcastle upon Tyne
NE15 8NZ

Tel: 0191 2642705 Email: <u>repairs@vet-direct.com</u>

The enclosed product has been sent to you for inspection. Please provide estimate to repair – please send estimate to <u>repairs@vet-direct.com</u>

Product:	ENVITEC	OKIQUA	5 0x	racon AJAL-15
Serial No:	A106091	A11079		
Accessories:				
Quantity:				
Condition:	neco			
Work requir	ed:			
Warranty:	Yes / No	5/5/23 PO	Number: 12	SITLI
Quotation r	equired? Yes/	No		



Service Repair Sheet 68608

Contact Name

Company/ Hospital Name

Position

Direct Phone General Phone

Opera Account

Email

Date Received Booked in By

Amanda Perry

Vet Direct Services Ltd

Purchasing Manager

0191 2642705

0191 2642705

00012824

Amanda.Perry@vet-direct.com

18/Oct/2023

Robert Connor

Repair

Ref

S/N

Equipment Type

Under Warranty

0111275 A106091 SRN36097

Oxygen Analyser

Time :0 Hour(s)

The OxiQuant S Oxygen analyser has been replaced under warranty with SN:A106408.

Repair

Ref

S/N

Equipment Type

Under Warranty

SRN36098

0110660 A110790

Oxygen Sensor

Time: 0 Hour(s)

Replaced with S/N A111197