

Service Repair Sheet SRS68613

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Mike Brampton

Thames Medical Ltd

Accounts

01903522911

01903522911

00011982

mike@thamesmedical.com

24/Oct/2023

Robert Connor

Viamed

Warranty

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☐

Cleaned by Viamed,
if no declaration certificate
from customer ☒

Signed: RC
Date: 24/10/23

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____
Date: _____

Notes sending in 0015000, s/n BN09004. ``90% of the time showing sensor fault or no sensor, then working on the VM-2500``
23/Oct/2023 Kate Griffiths
sending in 0015000, s/n BN09004. ``90% of the time showing sensor fault or no sensor, then working on the VM-2500``
24/Oct/2023 Robert Connor
Received 1 x clip sensor s/n BN09004

Ready For quote

Repair Complete Signed

CGreen 27-10-23

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36106	Pulse Oximetry Ear Clip Sensor	0015000	BN09004	Yes

0040003 x 1 FOC
Old S/N, SRS, SRN

0015000 x 1 FOC
New S/N, SRS, SRN

UPS x 1 FOC

Thames Medical Ltd

3 A Becket Gardens

Worthing, West Sussex BN13 2BW

www.thamesmedical.com

email info@thamesmedical.com

tel 01903 522911

fax 01903 522922

Experts in patient monitoring and anaesthesia



PURCHASE ORDER

order #

PO-01987

date

23/10/2023

vendor address Viamed Ltd

15 Station Road

Cross Hills

Keighley, West Yorkshire

BD20 7DT

contact

Kate

phone

01535 634542

fax

01535 635582

carrier

UPS

payment terms

Net 30

ITEM	DESCRIPTION	QUANTITY	UNIT PRICE	SPECIAL TAX RATE	SUB-TOTAL
TML-MISC	Faulty clip sensor for replacement under warranty period. SRS68613	1	£0.00	Taxable	£0.00

remarks


SRS68613

SUB-TOTAL £0.00

VAT £0.00

TOTAL £0.00

GQ 6475 4947 1GB SIGNED FOR



Please acknowledge this order and advise the delivery date by fax : +44 (0) 1903 522922 and/or by email:
info@thamesmedical.com

Service Repair Sheet 68613

Contact Name

Mike Brampton

Company/ Hospital Name

Thames Medical Ltd

Department

Accounts

Direct Phone

01903522911

General Phone

01903522911

Opera Account

00011982

Email

mike@thamesmedical.com

Date Received

24/Oct/2023

Booked in By

Robert Connor

Repair

Ref

S/N

Equipment Type

Under Warranty

SRN36106

0015000

BN09004

Pulse Oximetry Ear Clip Sensor

Parts Replaced

Time :0 Hour(s)

Qty: 1 0015000

The SpO2 lingual sensor has been replaced under warranty with SN:BN09008.
