

# Service Repair Sheet SRS68629

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Collette Bagas

Oxygen Therapy Centre

07829961546

01534737297

00012878

collette@oxygen.org.je

23/Nov/2023

Robert Connor

Viamed

Warranty

## VIAMEDclean

### Goods In Only

Decontamination  
certificate provided  
by customer ☐

Cleaned by Viamed  
if no declaration certificate  
from customer ☐

Signed: \_\_\_\_\_

Date: \_\_\_\_\_

### Goods Out Only

Cleaned by Viamed before  
returning to customer

Signed: \_\_\_\_\_

Date: \_\_\_\_\_

Notes 14/Nov/2023 Kate Griffiths

14/Nov/2023 Kate Griffiths

Faulty R-17MED, S/N: 782027. Not working. Under warranty. They have tried various ways to check, see attached

15/Nov/2023 Kate Griffiths

will send back today

23/Nov/2023 Robert Connor

Received 1 x R-17MED s/n 782027.

Ready For quote

Repair Complete Signed

CCN 27.11.23

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36153	Oxygen Sensor	0110017	782027	Yes

0140013 x 1 FOC

Old SIN, SRS, SRN

0110017 x 1 FOC

New SIN, SRS, SRN

UPS x 1 FOC

Please find the enclosed sensor.

Our returns reference number is SRS68629

Kind regards

Collette Bagas (Centre Manager)



**OXYGEN**  
THERAPY CENTRE

Service Repair Sheet 68629

Contact Name

Collette Bagas

Company/ Hospital Name

Oxygen Therapy Centre

Direct Phone

07829961546

General Phone

01534737297

Opera Account

00012878

Email

collette@oxygen.org.je

Date Received

23/Nov/2023

Booked in By

Robert Connor

---

Repair

Ref

S/N

Equipment Type

Under Warranty

SRN36153

0110017

782027

Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1

0110017

Replaced under warranty with S/N 938355

---