



Service Repair Sheet SRS68626

Contact Name	Dennis Vessey
Company/ Hospital Name	Dennis Vessey and Co
Department	Accounts
Position	
Direct Phone	01652688904
General Phone	01652688904
Opera Account	VST010
Email	dennis.vessey@btconnect.com
Order Number	
Date Received	08/Nov/2023
Booked in By	Catherine Spence
Main Company	VandagraphST
Type Return	Warranty

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☐

Cleaned by Viamed,
if no declaration certificate
from customer ☐

Signed: _____

Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 08/Nov/2023 Catherine Spence

08/Nov/2023 Catherine Spence

9 Sensors received

out of range with atmosphere compression

S/N ISC117543,ISC117552,ISC117560,ISC117561,ISC117562,ISC117568,ISC117572,ISC117580,ISC117588

08/Nov/2023 Catherine Spence

In engineers room

13/Nov/2023 Philip Crossley

Waiting for SN to speak to customer, all tested ok.

22/Nov/2023 Steve Nixon

After discussions with Dennis he has asked for the sensors to be returned back to him and agrees that the reported problem was likely due to the unusual spate of weather atmospheric pressure bombs.

Ready For quote

Repair Complete Signed

EGN 27.11.23

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36126	Oxygen Sensor VST	8010012	ISC117543	Yes
SRN36127	Oxygen Sensor VST	8010012	ISC117552	Yes
SRN36128	Oxygen Sensor VST	8010012	ISC117550	Yes
SRN36129	Oxygen Sensor VST	8010012	ISC117561	Yes
SRN36130	Oxygen Sensor VST	8010012	ISC117562	Yes
SRN36131	Oxygen Sensor VST	8010012	ISC117568	Yes
SRN36132	Oxygen Sensor VST	8010012	ISC117574	Yes
SRN36133	Oxygen Sensor VST	8010012	ISC117580	Yes
SRN36134	Oxygen Sensor VST	8010012	ISC117588	Yes

0140011 x 9
FOC

SN's SRS, SRN
No fault found

~~WPS~~

UPS x 1 FOC

Service Repair Sheet 68626

Contact Name	Dennis Vessey
Company/ Hospital Name	Dennis Vessey and Co
Department	Accounts
Direct Phone	01652688904
General Phone	01652688904
Opera Account	VST010
Email	dennis.vessey@btconnect.com
Date Received	08/Nov/2023
Booked in By	Catherine Spence

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN36126	8010012	ISC117543	Oxygen Sensor VST	No Fault Found Time :0 Hour(s)

No fault found - return to Dennis as agreed.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN36127	8010012	ISC117552	Oxygen Sensor VST	No Fault Found Time :0 Hour(s)

No fault found - return to Dennis as agreed.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN36128	8010012	ISC117550	Oxygen Sensor VST	No Fault Found Time :0 Hour(s)

No fault found - return to Dennis as agreed.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN36129	8010012	ISC117561	Oxygen Sensor VST	No Fault Found Time :0 Hour(s)

No fault found - return to Dennis as agreed.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN36130	8010012	ISC117562	Oxygen Sensor VST	No Fault Found Time :0 Hour(s)

No fault found - return to Dennis as agreed.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN36131	8010012	ISC117568	Oxygen Sensor VST	No Fault Found Time :0 Hour(s)

No fault found - return to Dennis as agreed.

Service Repair Sheet 68626

Contact Name

Dennis Vessey

Company/ Hospital Name

Dennis Vessey and Co

Department

Accounts

Direct Phone

01652688904

General Phone

01652688904

Opera Account

VST010

Email

dennis.vessey@btconnect.com

Date Received

08/Nov/2023

Booked in By

Catherine Spence

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN36132	8010012	ISC117574	Oxygen Sensor VST	No Fault Found Time :0 Hour(s)

No fault found - return to Dennis as agreed.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN36133	8010012	ISC117580	Oxygen Sensor VST	No Fault Found Time :0 Hour(s)

No fault found - return to Dennis as agreed.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN36134	8010012	ISC117588	Oxygen Sensor VST	No Fault Found Time :0 Hour(s)

No fault found - return to Dennis as agreed.
