

Service Repair Sheet SRS68529

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Lee Harper

Pinderfields General Hospital

Medical Physics Department

Technician

01924 541050

00001415

lee.harper@midyorks.nhs.uk

10/Aug/2023

Robert Connor

Viamed

Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☒

Cleaned by Viamed,
if no declaration certificate
from customer

Signed: _____

Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 27/Jul/2023 Steve Hardaker

27/Jul/2023 Steve Hardaker

Returning a TOF 3D with damaged screen. Sold on RVM135544-1, 18 Mar 2022. Still under warranty but may not be covered if physically damaged by mis-handling, check with SN if not obvious. serial number TBA.

10/Aug/2023 Robert Connor

Received 1 x TOF3D s/n T3D202002228, with complete patient cable and batteries.

No visible damage to face of unit or screen, screen shows a black line constantly. There is some small wear marks on the top end of the case.

Ready For quote

CGNEON 13.9.23

Repair Complete Signed

CGNEON 29.11.23

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35960	Microstim	2510091	T3D202002228	Yes

2540100 x 1 @ £650
S/N, SRS, SRN

- edit the value for
this one.

UPS x 1 @ £12.

£650. re
FOC carriage
cg 5.9.23
+ SNIXOR

Quote to S
Mechanical
/physical
damage