

Service Repair Sheet SRS68616

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Maneesh Ram

Kings College Hospital (use this o

Medical Equipment Management

Medical Equipment Engineer

02032991607

02032997878

00002990

maneesh.ram@nhs.net

02/Nov/2023

Catherine Spence

Viamed

Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☒

Cleaned by Viamed,
if no declaration certificate
from customer ☐

Signed: _____
Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____
Date: _____

Notes 25/Oct/2023 Steve Hardaker

25/Oct/2023 Steve Hardaker

Returning a MaxO2 ME for repair, it will not turn off when powered up. S/n EA01199005 sold 3/10/2019.

He has tried removing the batteries but the fault still occurs.

02/Nov/2023 Catherine Spence

Received unit(S/N:EA01199005) in with Sensor S/N HM50099102 and cable. no batteries included

Ready For quote

CGNEEN 3.11.23

Repair Complete Signed

CGNEEN 5.12.24

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36116	Oxygen Monitor	0111263	EA01199005	2
SRN36117	Oxygen Sensor	0110452	HM50099102	2
SRN36118	Misc. Cable	0131700		2

0140120 x 0.75hr @ £90 per hr = £67.50
S/N, SRS, SRN

R228P15 x 1 £21.75
SRS, SRN

*→
UPS x 1 £12.

0140011 x 1 FOC
S/N, SRS, SRN → SRN 36117

0140025 x 1 FOC → SRN 36118
SRS, SRN

} Add above carriage
line. Cg 5.12.23

Service Repair Sheet 68616

Contact Name	Maneesh Ram
Company/ Hospital Name	Kings College Hospital (use this one)
Department	Medical Equipment Management Service
Position	Medical Equipment Engineer
Direct Phone	02032991607
General Phone	02032997878
Opera Account	00002990
Email	maneesh.ram@nhs.net
Order Number	KFM0433424
Date Received	02/Nov/2023
Booked in By	Catherine Spence

Repair	Ref	S/N	Equipment Type	
SRN36116	0111263	EA01199005	Oxygen Monitor	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1 R228P15
Qty: 0.75 0140120

The unit had a faulty on/off switch.

I have replaced the keypad membrane. The unit has been tested and all keys are now working.

I have also checked the calibration of the unit and include a calibration certificate.

Repair	Ref	S/N	Equipment Type	
SRN36117	0110452	HM50099102	Oxygen Sensor	No Fault Found Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	
SRN36118	0131700		Misc. Cable	No Fault Found Time :0 Hour(s)

Purchase order



Supplier:
VIAMED LTD
15 STATION ROAD
CROSS HILL
KEIGHLEY
WEST YORKSHIRE
BD20 7DT
GBR

Deliver to:
Faraday Building,
124-126 Denmark Hill,
London
SE5 8RX
GBR

Invoice to:
KCH Interventional Facilities
Management LLP
Finance Department
Unit 1,129 Coldharbour Lane
London
SE5 9NY
GBR

PO Number	KFM0433424
Date	27/11/2023
Ordered by	Tamara Boake
Currency	GBP

Purchasing Support
KFM
Unit 1, 129 Coldharbour Lane
London
SE5 9NY
GBR
020 3299 7878
kch-tr.ask-kfm@nhs.net

invoices@KFM.onmicrosoft.com
020 3299 7878

Subject to standard NHS terms and conditions of contract. For more information see <https://health-family.force.com/s/termsandconditions>
Where a contract reference is quoted below, those Terms and Conditions will take precedence. Copies available upon request. All relevant COSHH data must be provided where applicable. Incoterms Delivery Term: DDP(agreed Contract Terms will take precedence)

Line No.	Supplier Product Code	External item number	Description	Notes	Expected delivery date	Unit of Purchase	Quantity	Price per Unit (GBP)	Net Value (GBP)
1		Repair	Repair Maxtec oxygen monitor s/n EA01199005, ID 77-553.	Repair WO300731 from Thomas Cook & PHDU, as per attached quote no. QVM146486, dated 03/11/2023.	27/11/2023	EACH	1.00	101.25	101.25
Total Value (Net)									101.25

We are a fully owned subsidiary of King's College Hospital. Invoices must be raised in the name of KCH Interventional Facilities Management LLP.
For queries regarding the setup of new accounts to support King's FM please contact 0203 299 7878