Service Repair Sheet SRS68647

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Andrew Kelly

Whiston Hospital

**EBME** Department

Senior Medical Engineer / Deputy

0151 290 4294

01514261600

00002152

Andrew.Kelly@sthk.nhs.uk

13/Dec/2023

Robert Connor

Viamed

Warranty

VIAN	M€D <b>cl</b> e	ean
Decontai	e provided	/ 🗆
	by Viamed, ation certificate mer	
Cleaned	Out Only by Viamed be to customer	

Notes 08/Dec/2023 Steve Hardaker 08/Dec/2023 Steve Hardaker Returning 2 pairs of R-22Vi failed under warranty. S/n V106341&2 - sold 08 Feb 2023 still under warranty. S/n V106215&6 - sold 24 Jan 2023 still under warranty. 13/Dec/2023 Robert Connor Received 4 x R22Vi s/n V106215, V106216, V106341, V106342.

Ready For quote

Repair Complete Signed

careen 13-12-23

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36162	Oxygen Sensor	0110072	V106215/V106216	Yes
SRN36163	Oxygen Sensor	0110072	V106341/V106342	Yes

0140013 × 2 010 S/N's SRS, SRN

0110072 × 2 New SIN's ses SEN

UPS X 1 FOC



## Mersey and West Lancashire Teaching Hospitals NHS Trust

Medical Engineering,
Whiston Hospital,
Prescot,
Merseyside,
L35 5DR

0151 430 1273 andrew.kelly@sthk.nhs.uk

08/12/2023

Viamed Limited, 15 Station Road, Cross Hills, Keighley, West Yorkshire, BD20 7DT

REF: \$8368647

Dear Steve,

Please find enclosed matched pair of Viamed R-22vi cells (S/n V106341&2, S/n V106215&6). They have failed in use and have been in use since February and March. I would like to return under warranty for replacement as discussed via email.

Regards,

Andrew Kelly (Deputy Manager Medical Engineering) Service Repair Sheet 68647

**Contact Name** 

Company/ Hospital Name

Department

Position

**Direct Phone** General Phone

Opera Account

Email

Date Received

Booked in By

Andrew Kelly

Whiston Hospital

EBME Department

Senior Medical Engineer / Deputy Manager 0151 290 4294

01514261600

00002152

Andrew.Kelly@sthk.nhs.uk

13/Dec/2023

Robert Connor

Repair

Ref

S/N

Equipment Type

Time: 0 Hour(s)

Parts Replaced

SRN36162

Qty: 1

0110072

0110072 V106215/V1062160xygen Sensor

Replaced under warranty with S/N V107290 / V107291.

Repair

Ref

S/N

**Equipment Type** 

**Under Warranty** 

**Under Warranty** 

SRN36163

0110072 V106341/V1063420xygen Sensor

Time: 0 Hour(s)

Parts Replaced

Qty: 1

0110072

Replaced under warranty with S/N V107292 / V107293.