

Service Repair Sheet SRS68597

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Vaisakh Sasikumar

Royal Brompton and Harefield
Clinical Engineering Department
Technical Support Technologist

01895823737

00002790

V.Sasikumar@rbht.nhs.uk

16/Oct/2023

Robert Connor


Viamed

Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer



Cleaned by Viamed,
if no declaration certificate
from customer

Signed: _____

Date: _____



Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 09/Oct/2023 Kate Griffiths

09/Oct/2023 Kate Griffiths

Faulty MySign O, 0111276, s/n 101312 - faulty display, so when trying to turn on the alarms can be heard but no display, battery has been replaced.

10/Oct/2023 Steve Hardaker

Additional info: Manufactured Jan 16. Envitec suggested it could be that the battery it's definitely not as he bought a new one from us and replaced it, did a full charge and it's doing the same. Also cant be the keypad as it turns on and off and he can hear the alarms, looks like it's a display fault. SN said we can quote for repair without any evaluation fee as he wants to get more info on this failure.

16/Oct/2023 Robert Connor

Received 1 x MySign O s/n 101312, with coiled cable, OOM111 s/n A122032, flow diverter, and blue tee.

Ready For quote

CANEEN 6.12.23

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36068	Oxygen Monitor	0111276	101312	22
SRN36069	Oxygen Sensor	0111560	A122032	22

0140141

~~0140000~~ x 1

@90p/hr charge 1/4 hr.

1/4 hr

S/N, SRS, SRN

0140011

S/N, SRS, SRN

UPS

x 1

FOC
SRN36069

← please Add.

@ £12.

Service Repair Sheet 68597

Contact Name

Company/ Hospital Name

Department

Position

General Phone

Opera Account

Email

Date Received

Booked in By

Vaisakh Sasikumar

Royal Brompton and Harefield

Clinical Engineering Department

Technical Support Technologist

01895823737

00002790

V.Sasikumar@rbht.nhs.uk

16/Oct/2023

Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN36068	0111276	101312	Oxygen Monitor	Complete - Repaired Time :0.25 Hour(s)

Parts Replaced

Qty: 0.25 0140141

Repair	Ref	S/N	Equipment Type	
SRN36069	0111560	A122032	Oxygen Sensor	No Fault Found Time :0 Hour(s)

The OOM111 Oxygen sensor has been tested. No fault was found.

Guy's and St Thomas' NHS Foundation Trust		NHS		Contact Reference: CPC [142712]RBH Contact Name: Shalarie Fontaine Contact Number: Email Address: s.fontaine@rbht.nhs.uk		Purchase Order Date: 13-DEC-2023 Page Number: Page 1 of 1 Revision Number: 0		Purchase Order Order Number RJ1-1240426		
VIAMED 15 STATION ROAD CROSS HILLS KEIGHLEY WEST YORKSHIRE BD20 7DT		Deliver to: 000037 : Brompton Stores Loading Bay Goods Inwards Goods will only be received between 8:00 and 16:00 Mon to Fri Brompton Stores Loading Bay (Goods Inwards) Royal Brompton Hospital Sydney Street London SW3 6NP UNITED KINGDOM		Invoice To: Guy's Hospital PO Box 147 Great Maze Pond London SE1 9RT UNITED KINGDOM EORI:GB654923417000 (Excludes NI) Invoices to: supplierinvoices@gstt.nhs.uk Statements and queries to Accounts payablequeries@gstt.nhs.uk						
Tel: +44 (01535)01535634542 Fax:		Tel:								
Notes to supplier: Quotation QVM147105		Settlement terms: 30 Days								
Line No	Qty	Unit of Purchase	Description	Supplier Item Code	Req.No	Internal Contract Reference	Unit Price exc VAT GBP	Value exc VAT GBP	VAT GBP	Required Delivery Date
1	1	EACH	Labour Charge - Repair of Oxygen Monitor Quotation QVM147105	S/N: 101312,	RBH-510010688-REQ		22.50	22.50	4.50	15-Dec-23
2	1	EACH	Carriage Note To Supplier : FAO Clinical Engineering. Please contact s.fontaine@rbht.nhs.uk on receipt of this PO. Many thanks		RBH-510010688-REQ		12.00	12.00	2.40	15-Dec-23
Total Order Value							34.50	6.90		

Notes:

- The above Purchase Order Number must be quoted on all the invoices, delivery notes and other correspondence. Failure to do so may result in rejection of goods or delay in payment.
- This order is issued in accordance with our standard terms and conditions, copies of which are available on request.
- If there are any queries, please contact the buyer prior to processing this order.
- EORI: GB654923417000 must be replaced when trading with Northern Ireland (NI) by X654923417000.