Service Repair Sheet SRS68648

Contact Name

Atif Hussain

Company/ Hospital Name

Luton & Dunstable Hospital

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

01582497042

01582 497042

00003490

atif.hussain@ldh.nhs.uk

13/Dec/2023

Robert Connor

Viamed

Quote

VIAMEDCIE Goods In Only Decontamination certificate provided by customer	ean
Cleaned by Viamed, if no declaration certificate from customer Signed:  Date:	<u> </u>
Goods Out Only Cleaned by Viamed be returning to customer Signed: Date:	fore

Notes 11/Dec/2023 Aqib Majeed

11/Dec/2023 Aqib Majeed

The customer has a Capnograph VM-2500s and said it sometimes doesn't pick the reading up of the CO2 and wants us to check and repair. SN number is A1711160013

13/Dec/2023 Robert Connor

Received 1 x VM-2500-S s/n A1711160013, with 4 x AA battery and silicone cover.

Ready For quote

CGNOON 21-12-23

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36164	Capnograph	4410520	A1711160013	2

4440000 XI @ 0.5hr £90 per hour 5/N, 5RS, SRN.

4430201 × 1 2 E15 SRS, SRN

UPS X 1 0 E12.



### Decontamination Form

Reference: SERVICEJOB\_87440

Work Requested: 12 Month Service

Date: 11/12/2023

#### Hospital

Hospital	Luton & Dunstable University Hospital		
Address	Lewsey Road, Luton, LU4 0DZ		
Phone Number	01582 718 369		
Email Address	CEWorkshop@ldh.nhs.uk		

#### Device

Asset no	LUT31415		
Serial Number	A1711160013		
Model	VM-2500-S		
Description of device	Carbon dioxide monitor		

#### Sender

Name	Atif Hussain	
Signature		
Position	Clinical Engineer	


#### Receiver


FAO	Service/Repairs department		
Company	VIAMED		
Reference			


The state of the s 18 ISO Tasks | My Requests 20.00 °C Search


RS Full, ZT Full, EH Full, EC Full, RC Full, PC Full, AM Full

































# Luton & Dunstable Hospital

Documents

**Files** 

CID15137 Opera 00003490 Type:NHS **Hospital End User** Luton & Dunstable Hospital Lewsey Road, , Luton, Bedfordshire, LU4 0DZ, UK Tel 01582 497042 GBP End User (0001)

Dog Call | Add Issue

Credit Credit Limit 0.00GBP

Account Main Home Details Distributor Agreements

Account Memos

M Sales History Linked

Issues

Stock References O Cust./Supp. Returns

\* Service **Visits** 

Regulatory Agreements

Use:0001 GBP End User

Repair SRS68648 Values in Pounds @ 1: 1.00

SRN36164	Capnograph	4410520		——	
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		4430201	1	£15.00	
		4440000	0.5	£90.00	£45.00
				Parts Cost	£60.00

## Page updated, TRipple check prices to price in intrastats main search

CHECK PRICES BEFORE SENDING QUOTE

**Quote Sent**