

JG Full, ML Full, EH Full, MG Half , EC Full, PC Full, SH Full, ZT Full, RC 07:45:00 AM For 3.5 Hours, AM Full



Charles Potter

 CID27246 Opera CID27246 Type:Vandagraph Retail
Charles Potter Moor End, Irton, Holmrook, , CA19 1YQ, United Kingdom
Tel 01946724083 GBP Retail Price List Vandagraph (0010) 

Add Issue

Proforma Credit Limit 0.00GBP

The diagram illustrates a navigation menu layout. It consists of two rows of buttons. The top row contains: Account Home, Main Details, Account Memos, Sales History, Stock References, Cust./Supp. Returns, Service Visits, and Distributor Agreements. The bottom row contains: Documents Files, Linked Issues, and Regulatory Agreements. The buttons are arranged in a staggered fashion, with some spanning multiple columns.

SRS68649

SRS Created : 12 Dec 2023

Created By Ryan Swaine

Add Watch

[Print Barcodes](#)

[Print A4 Sheet](#)

Split Items into Different SRS Numbers

Upload Document to SRS

Handle with care

Add Items to Supplier Returns Box

Add

☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs

☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

Add Notes

ADD DOCUMENT TO SRS : Document Description	Choose a file to upload: Choose file No file chosen
Next	

Service Repair Sheet 68649		Notes
SELECT * FROM viamedquoteaddress where ID='27246'		12/Dec/2023 Ryan Swaine
Company / Hospital	Charles Potter	12/Dec/2023 Ryan Swaine
Contact Name	Charles Potter	Ordered an R-22VAN, but it should have been a R-22SHO. To exchange for an R-22SHO without any additional charge as a good will gesture
Department		14/Dec/2023 Robert Connor
Position		Received 1 x R-22VAN s/n 102948
Company Phone	01946724083	
Direct Phone	01946724083	
Opera Account	CID27246	
Email	c.potter13@btinternet.com	
Order Number		
Viamed ORD Number		
Date Received Into building	14 Dec 2023	
Issues?		

Items for Repair

...

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN36165	Oxygen Sensor Vandagraph	0110232 Requires Service Manual Linking in System	 2286423	102948	Oxygen Sensor R-22VAN	Yes	No	Unfinished		00:00

Currently Viewing ITEM SRN36165 Oxygen Sensor Vandagraph 0110232 102948 Oxygen Sensor R-22VAN

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Non Supplied	Non added Yet	Non added Yet

-

ISO REVIEW

Please Select

Instructions