Service Repair Sheet SRS68669

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Wendy Rintoul

Wrexham Maelor Hospital

Medical Engineering

Administrator

01978 725869

01978291100

00005500

Wendy.Rintoul@wales.nhs.uk

09/Jan/2024

Robert Connor

Viamed

Quote

Goods Decontar	e provided
	by Viamed, ation certificate ner
Cleaned	Out Only by Viamed before to customer

Notes 08/Jan/2024 Aqib Majeed 08/Jan/2024 Aqib Majeed

customer is returning an MX300-I monitor to us, SN: 299934. the device doesn t read and the screen is flashing 09/Jan/2024 Robert Connor

Received 1 x MX-300i s/n 299934, coiled cable s/n 0003081, R-17MED s/n 179767, with flow diverter.

Ready For quote

Careen 16.1-24

Repair Complete Signed

		V		
SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36212	Oxygen Monitor	0111235	299934	2
SRN36213	Misc. Cable	0131202	0003080	12
SRN36214	Oxygen Sensor	0110017	179767	10

6140005

SHOOH XI RO

SIN, SRS, SRN

NO FAUIT FOUND.

OHOOZS XI RO

SIN, SRS, SRN

NO FAUIT FOUND.

OHOOIZ XI RO

HO SIN, SRS, SRN

Fauity

OHOOIT XI D RS3

SRS, SRN

DPS XI D RIZ.

5268669



Bwrdd Iechyd Prifysgol Betsi Cadwaladr University Health Board Medical Engineering, Dept 28
Wrexham Maelor Hospital, Croesnewydd Road
Wrexham,
LL13 7TD

Viamed Ltd. 15 Station Road Cross Hills Keighley West Yorkshire BD20 7DT

Ein cyf / Our ref: OXM055

Eich cyf / Your ref: SN 299934

**2**: 01978 725869

Gofynnwch am / Ask for: Wendy Rintoul

Ffacs / Fax:01978 727337

E-bost / Email: wendy.rintoul@wales.nhs.uk

Dyddiad / Date: January 8, 2024

Dear Sir/Madam

RE: Oxygen monitor MX300-I SN 299934 SR68669

Please find enclosed the above unit for quotation for repair: the unit is not functioning correctly, it's not reading and the screen is flashing.

Do not hesitate to contact me with any queries.

Many thanks

Yours faithfully

WPinton 1

Wendy Rintoul Support Assistant