Service Repair Sheet SRS68653

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Lucy Gardener

Royal Victoria Infirmary

Electronics and Medical Engineeri

Support Technician

01919177216

01912336161

00003785

lucy.gardener@nhs.net

20/Dec/2023

Robert Connor

Viamed

Quote

VIAMEDclean Goods In Only Decontamination certificate provided by customer

Cleaned by Viamed, if no declaration certificate from customer

Signed: Date:

Goods Out Only

Cleaned by Viamed before returning to customer

Signed:

Date:

Notes Tom Thumb to send in for "servicing and repair". S/N R007, "copper washer is stick fast and it has a badly dama dial". Aware will probably need a new dial

19/Dec/2023 Kate Griffiths

Tom Thumb to send in for "servicing and repair". S/N R007, "copper washer is stuck fast and it has a badly damaged d Aware will probably need a new dial

20/Dec/2023 Robert Connor

Received 1 x tom thumb, gauge not attached, gauge face missing, gauge body and dial bent, no serial number label. Customer reports unit is s/n R007.

Ready For quote

CGreen 4-1-24

Repair Complete Signed

CGreen 16-1-24

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36196	Tom Thumb	0310030	R007	7

0380000 × 1 2 190 5/N, ses, sen

0330212 x 1 E2.20 Ses, sen

0330203 × 1 E125. ses, sen

OPS > 10 E12

Service Repair Sheet 68653

Contact Name

Lucy Gardener

Company/ Hospital Name

Royal Victoria Infirmary

Department

Electronics and Medical Engineering Department

Position

Support Technician

Direct Phone

01919177216

General Phone

01912336161

Opera Account

00003785

Email

lucy.gardener@nhs.net

Order Number Date Received RTDN400350487 20/Dec/2023

Booked in By

Robert Connor

Repair

Ref

S/N

**Equipment Type** 

SRN36196 0310030 R007

Tom Thumb

Complete - Repaired

Time :0 Hour(s)

Parts Replaced

Qty: 1

0380000

Qty: 1

0330212

Qty: 1

0330203

Tom Thumb TT480 R007 has been stripped and cleaned then reassembled with new O rings and new gauge. The two valves have been checked and reset before QA.

I have added a serial number label and transplanted the asset number label to the gauge. The asset number label might not be as sticky as it once was.

# Order

#### **BILL TO ADDRESS**

ACCOUNTS PAYABLE LEVEL 2 REGENT POINT REGENT FARM ROAD NE3 3HD NEWCASTLE UPON TYNE,

GLN: 5055208700004 (GLN, Endpoint ID)

Christina Bulch christina.bulch@nhs.net Order number
Date
Validity
Contract

RTDN400350487 2024-01-11

QUO QVM147526

#### Seller

### **Viamed Ltd**

15 Station Road

BD207DT Cross Hills, Keighley, West Yorkshire

United Kingdom

GLN: 5051826000007 (GLN, Endpoint ID)

GLN: 5051826000007 (0088)

#### Receiver

## The Newcastle upon Tyne Hospitals NHS Foundation Trust

Regent Point Regent Farm Road Gosforth

NE7 7DN Newcastle upon Tyne,

United Kingdom

GLN: 5055208700004 (GLN, Endpoint ID)

GLN: 5055208700004 (0088)

#### Delivery

#### 1 910G76 MEDICAL ELECTRONICS DEPT

910G76 MEDICAL ELECTRONICS DEPT ROYAL VICTORIA INFIRMARY, QUEEN VICTORIA ROAD NE1 4LP NEWCASTLE UPON TYNE,

United Kingdom

## Delivery place ID:

5055208701469

## Delivery place:

1 910G76 MEDICAL ELECTRONICS DEPT

Line	Product	Description	Quantity	Unit price	Total
#1	EME	ANNUAL SERVICE OF TOM THUMB SERIAL NUMBER R007 AS PER ATTACHED QUOTATION QVM147526 INCLUDING SPARE PARTS & DELIVERY	1.0 EA	229.20	229.20 GBP

#### Notes

QUOTATION QVM147526 REFERS