

Service Repair Sheet 68670

Contact Name

Company/ Hospital Name

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Lisa Vickers

Medivent Ltd (Euro)

016280338

0035316280338

00007374

info@medivent.ie

7689

18/Jan/2024

Repair	Ref	S/N	Equipment Type
SRN36224	1410000	PR0308A16	Foetal Simulator

Complete - Repaired
Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000

Qty: 1 1430309

Qty: 1 1430288

V1000 has had transducer interface cushion and battery contacts replaced. Calibration has been checked.
