

Service Repair Sheet 68677
Contact Name
Company/ Hospital Name
General Phone
Opera Account
Email
Date Received
Booked in By

Becky Watson
Royal Devon and Exeter
01392 41 16 11
00001700
becky.watson@nhs.net
24/Jan/2024
Robert Connor

Repair	Ref	S/N	Equipment Type	No Fault Found
SRN36226	0111235	338702	Oxygen Monitor	Time :0 Hour(s)

The MX300i Oxygen monitor has been tested. No fault was found.

Repair	Ref	S/N	Equipment Type	No Fault Found
SRN36227	0131202	0000964	Misc. Cable	Time :0 Hour(s)

The Oxygen sensor cable has been tested. No fault was found.

Repair	Ref	S/N	Equipment Type	No Fault Found
SRN36228	0110017	917480	Oxygen Sensor	Time :0 Hour(s)

Under Warranty

The R-17MED Oxygen sensor has been tested in air and Oxygen. No fault was found.
