Service Repair Sheet 68662

Contact Name

Company/ Hospital Name Department

Position Direct Phone General Phone Opera Account

Email

Order Number Date Received Booked in By

Erizal Domingo

Addenbrookes Hospital Clinical Engineering Medical Technologist

01223216606 01223245151 00000860

erizal.domingo1@nhs.net

PO-000236823 04/Jan/2024 Robert Connor

Repair SRN36200 1410000 PR02380A11

Ref S/N

Equipment Type Foetal Simulator

Complete - Repaired Time: 0 Hour(s)

Parts Replaced

Qty: 1 1480001

V1000 has had calibration checked