

Service Repair Sheet 68691
Contact Name Derek Smith
Company/ Hospital Name Vet Direct Services Ltd
Department Repairs Department
Position Technical Support Co-Ordinator
General Phone 0191 2642705
Opera Account 00012824
Email derek.smith@vet-direct.com
Date Received 14/Feb/2024
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN36266	0111275	A106340	Oxygen Analyser	
Parts Replaced				Time :0 Hour(s)
Qty: 1 0111275				

Replaced under warranty with S/N A106361 that includes oxygen sensor S/N A111150.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN36267	0110660	A111129	Oxygen Sensor	
				Time :0 Hour(s)

Replaced under warranty with S/N A106361 that includes oxygen sensor S/N A111150.
